APPENDIX 6

Asbestos Determination Certification (BBS-2536)



Signature

Asbestos Determination Certification

Structure Identification

	Structure Number(s) (000-0000): 062-0036								
Asbes	tos De	etermination							
	1.	The identified structures are included in the list that the USEPA exempted from the asbestos notification requirements in its letter of October 19, 2001.							
P	2.	The identified structures were unconfirmed for asbestos involvement as of October 19, 2001 but have subsequently been determined, on the basis of information available in the District office, not to involve asbestos in a bituminous bridge deck wearing surface or waterproofing membrane.							
	3.	The identified structures were unconfirmed for asbestos involvement as of October 19, 2002 but have subsequently been determined, through testing, not to involve asbestos in a bituminous bridge deck wearing surface or waterproofing membrane. The test results were obtained in conformance with the approved "Sampling and Testing Procedures for Asbestos in Bituminous Bridge Deck Wearing Surface or Waterproofing Membrane" (Attachment 2 to BDE Procedure Memorandum 26-02).							
	4.	The identified structures have been determined to involve asbestos in a bituminous bridge deck wearing surface and/or waterproofing membrane. The District will ensure compliance with the asbestos notification requirements for work on these structures that could disturb the asbestos-containing materials. The District also will ensure that the special provision for "Asbestos Waterproofing Membrane and Asbestos Bituminous Concrete Surface Removal (BDE)" is included in any contract for demolition of these structures or for other work involving removal of the existing bituminous bridge deck wearing surface and/or waterproofing membrane.							
	5.	The identified structures had been determined to involve asbestos in a bituminous bridge deck wearing surface and/or waterproofing membrane. Removal operations have been completed for all asbestos bituminous concrete surface and asbestos waterproofing membrane on the identified structures.							
Certif	ication	1							
Name	:	Jost Jochums Position Title: CE V							
Office	Addre	ess: 401 MAIN ST.							
		PEORIA, IL Phone Number: (309) 671 3333							
	Phone Number: (309) 671 3333								

APPENDIX 7

Bike/Ped Warrant Analysis

IL18 RIVER BRIDGE PROJECT PEDESTRIAN AND BICYCLE WARRANT MEMO

1.0 Introduction

As part of the IL 18 Illinois River Bridge Project, an assessment of bicycle and pedestrian needs through the project area was conducted to determine what bicycle and pedestrian accommodations are warranted. This assessment was conducted in accordance with Chapter 17 of the IDOT Bureau of Design and Environment (BDE) Manual.

2.0 Pedestrian Accommodations

Through the project area, sidewalks are present along both sides of IL 18 between 3rd Street and Front Street. East of Front Street, there are no sidewalks along IL 18 through the rest of the project area. Under the Preferred Alternative, sidewalks will be provided along both sides of IL 18, west of 2nd Street, where IL 18 rejoins the existing street network. East of 2nd Street, IL 18 will be shifted to the north and elevated above existing ground. The existing sidewalk on the south side of IL 18 will be reconstructed at its present location. On the north side of IL 18, all the properties between 2nd Street and Front Street will be acquired for the proposed improvements, and no sidewalk will be provided through this area. Additionally, new sidewalk will be provided along the east side of Front Street from a point approximately 100 feet south of IL 18 and extending to the north and under the proposed IL 18 to Cromwell Drive.

IL 18 through the project area is classified as a rural roadway. According to the BDE Manual, pedestrian accommodations do not have to be considered in a rural context. However, for the project area east of Front Street, the Pedestrian Warrants – Needs Assessment was completed since there are existing sidewalks at the west end of the project area, and there has been interest from the Community Advisory Group regarding pedestrian accommodations.

Based on the analysis, none of the pedestrian warrants are met. Therefore, no pedestrian accommodations will be provided along IL 18, east of Front Street. Table 1 summarizes this assessment.

ABLE 1 - PEDESTRIAN WARRANTS - NEEDS ASSESSMENT	
Warrant	Is the Warrant Met?
There is current evidence of frequent pedestrian activity.	No. There is no indication that there is frequent pedestrian activity along IL 18 across the bridge or east of the river. There are no sidewalks present along IL 18 through the project area, east of Front Street, and the total roadway width across the bridge is 22.6 feet. Both of which would deter pedestrian activity. However, there are no pedestrian travel generators on the east side of the river.
There is a history of pedestrian-related crashes.	No. Crashes in the project area between 2016 and 2020 were reviewed. Through this period, there was one pedestrian crash. This incident occurred along IL 18 near 2^{nd} Street and Front Street, where a pedestrian crossed the street and ran into a car.
The roadway improvement will create a safety impediment to existing or anticipated pedestrian travel (e.g., adding lanes so that the improvement itself acts as a barrier to pedestrian traffic).	No. The proposed improvements will not create a safety impediment along IL 18. There is little to no pedestrian travel along IL 18, east of Front Street.
There is urban or suburban development that would attract pedestrian travel along or immediately adjacent to the route to be improved.	No. IL 18 is classified as a rural roadway. There is no urban or suburban development along IL 18 east of the river.
Pedestrian-attracting development is expected along the route within five years of completion, either as documented in a local plan or anticipated as a factor of similar development history.	No. there is no known planned development along the east side of the river that would generate pedestrian traffic.
The roadway provides access to a park, recreation area or other significant destination, or across a natural or man-made barrier, within contexts other than rural.	No. IL 18 crosses the Illinois River which is a natural barrier. However, as noted above the project is considered to be in a rural setting, and therefore, this warrant is not met.

3.0 Bicycle Accommodations

To assess the need for bicycle accommodations on the project, a Bicycle Travel Assessment (BDE 1702) was completed (Attachment A).

As shown on the form, a number of bicycle travel generators (residential areas, park/recreation areas, churches, schools, library, downtown shopping district, employment centers, government offices, local businesses, and industrial plants) are present in the project vicinity. However, all of these generators are located on the west side of the river within the City of Henry.

Based on the results of the Bicycle Travel Assessment, the project meets Bicycle Travel Warrant 4: Does the project provide access across a river, railroad, highway, corridor, or other natural or man-made barrier? The IL 18 River Bridge provides access across the Illinois River.

According to the Bicycle Facility Selection Table (BDE Manual Figure 17-2.A), a four-foot paved shoulder should be provided as the bicycle accommodation for this project (Attachment D). However, to better accommodate wide farm equipment, to improve Bicycle Level of Service, to provide refuge for stalled vehicles on a two-lane long bridge, and to provide greater flexibility for traffic control for future maintenance activities, an eight-foot shoulder is recommended. The projected Bicycle Level of Service ranges from A (with an eight-foot shoulder) to D (with a four-foot shoulder). The following assumptions were made on form BDE 1703 (Attachment E) to determine the Bicycle Level of Service:

- Pavement Rating (CRS): 5
- Posted speed limit: 45 mph on the bridge
- Projected Average Daily Traffic: 2,900 (The 2019 ADT on the IL 18 Illinois River Bridge is 2,200. A 1.0% annual growth rate was used to increase the existing traffic volume to a 2045 design year.)

The eight-foot shoulder will be provided along IL 18 from 2nd Street to the eastern project limits. West of 2nd Street, the pavement will be 30 feet wide and striped for 12-foot travel lanes in each direction which will leave three feet on the outside for bicycle travel.

ATTACHMENT A

Bicycle Travel Assessment (BDE 1702)



Bicycle Travel Assessment

Reset Form

E-mail



То	F	rom			Date	
					06/10/24	C.
Route		Sectio	n Number		County	
FAP 653 (IL 18)		(104	B-D)BR		Marshall	v
Contract Number Job Numb	er			TIP Number		
68F09 P-94-007	7-20/D-94	-041	-19			
Project Limits			Call of City	551		
The intersection of IL18/3rd Street in Her	nrv on the	wes	t and the intersection	n of IL 18/IL 26 or	n the east.	
Project Description	,					
Region 3 / District 4 has assessed in or within one mile of a municipality with a popula			bicycle travel needs for	the referenced projec	t, which is $oxtimes$ / is no	ot 🗌
Checklist for bicycle travel generators in projec		Ť				
Generator	Yes	No			100000	s No
Residential Areas	X		Shopping Center			
Parks Recreation Areas			Hospitals			
Churches			Employment Centers Government Offices			
Schools			Local Businesses			1.1
Libraries			Industrial Plants		×	-
Existing Bicycle Trails		X	Public Transportation F	acilities		
Planned Bicycle Trails		X	Other			
Checklist for organizations and public coording	ation					
Organization	Yes	No	Organization		Ye	s No
Illinois Department of Natural Resources		X	Ride Illinois			
Local Municipalities			Local Bicycle Clubs, A	lvocacy Groups	\triangleright	
Park or Forest Preserve Districts		X	Active Transportation	Iliance (District 1 only	<i>'</i>)	
Metropolitan Planning Organization (if applicable)		X				
Sub-Regional Planning Council (as appropriate)		X	Other			

Summary of comments received


A local bicycle group, Illinois Valley Wheelm'n attended a stakeholder meeting. They requested that the existing bridge be left in place for bikes. If that cannot occur, then accommodations should be made on the new bridge for bikes. They stated that if the bridge is rehabilitated or replaced, the approaches need to be addressed as well. Nine to ten-foot wide lanes should be used for the bikes so that if the riders meet each other on the path, they have room to pass. Also, they stated that a barrier, like a concrete barrier wall, needs to be between the bikes and the cars. They stated it is important to have a dedicated lane for cycling. Scuppers and drains on the bridges are a problem. Their preference is to have at a minimum six-foot to nine-foot shoulders with a barrier. If there is no barrier, then eight-foot to nine-foot shoulders would be adequate.

Bicycle travel warrants: Warrant 1: Is the highway or street designated as a bikeway or recommended bike route in a regionally or locally adopted bike plan or shown in a regionally or locally adopted map as a recommended bike route? Yes No
Describe the designation
Warrant 2: Will the projected two-way bicycle traffic volume approximate 25 ADT or more during the peak three months of the bicycling season five years after completion of the project? Yes No
Estimating method
US Census Data: Table B08301 (Means of transportation to work) 2019 data for zip codes 61336 and 61537 (see attached). Projected bicycle ADT is 0.
Warrant 3: Does the route provide access to a park, recreational area, school, or other significant destination? Yes No
Destinations
Warrant 4: Does the project provide access across a river, railroad, highway, corridor, or other natural or man-made barrier? Yes No Barriers
Illinois River
Warrant 5: Will the highway project negatively affect the recreational or transportation utility or an independent bikeway or trail? Highway projects will negatively affect at-grade paths or trails when they are severed, when the projected roadway traffic volumes increase to a level that prohibits safe crossing at-grade, or where the widening of the roadway prohibits sufficient time for safe crossing. Yes No Bikeway(s) affected
If any of the five warrants above are met, the Department shall provide on-road or off-road accommodations for bicycle travel. Roadway improvement corridors should also be assessed with respect to adjacent/contiguous routes
Warrant 4 is met.
The following bicycle network considerations apply
The IL 18 River Bridge is on the Northern Tier bike route. This bike route crosses the northern half of the US starting in Washington and ending in Maine. The route is divided into 11 sections, with maps for each section of the route available online (www.adventurecycling.org). Section 8 of the bike route passes through Henry, utilizing the IL 18 Bridge over the Illinois River. The route can be ridden from late spring to late fall.
Accommodation type(s) identified as in the Bicycle Facility Selection Table
Four-foot paved shoulder
Accommodations proposed
Eight-foot paved shoulder to provide better Bicycle LOS, to accommodate wide farm equipment, provide refuge for stalled vehicles on a two-lane long bridge, and provide greater flexibility for traffic control for future maintenance activities.
Key connections to be provided with this project
The bicycle accommodation will provide access across the Illinois River.

Reasons for lesser accommodations (highes	t/best or none)
Discords 100 information (for an analysis	and the sitting and the DDE 4700)
Bicycle LOS information (for on-road non-sep	
Four-foot paved shoulder, LOS=D; S	Six-foot paved shoulder, LOS=C; Eight-foot paved shoulder, LOS=A.
Local coordination has been completed with	
	Name of the Local Agency
	ept the maintenance of the facility in accordance with requirements outlined in Chapter 5 of the has not) passed a resolution indicating the accommodation does not fit with their olution, when applicable.
Additional justification of accommodation ded	cisions, if applicable
X By checking this box and typing my name	e below, I verify that I have reviewed and concur with the information provided.
Name ,	Date
Neil Slowinski	6/11/2024
CC: Bicycle and Pedestrian/ADA Policy Engi	neer

Attachments

Insert an image below or attach a map to the form illustrating generators and travel paths. Show and describe where bicyclists would cross or ride parallel to the project.



ATTACHMENT B

US Census Data

Table B08301 - Means of Transportation to Work

American Community Survey

B08301 | MEANS OF TRANSPORTATION TO WORK

Universe: Workers 16 years and over



Notes 2 Geos 1 Year Topics Surveys Codes Hide	Transpose Margin of Error Rest	ore Excel Download Print	Мар			
	ZCTA5 61336 ZCTA5 61537					
Label	Estimate	Margin of Error	Estimate	Margin of Error		
➤ Total:	233	±63	1,217	±115		
Car, truck, or van:	227	±63	1,118	±115		
Drove alone	227	±63	989	±109		
✓ Carpooled:	0	±11	129	±58		
In 2-person carpool	0	±11	94	±51		
In 3-person carpool	0	±11	30	±24		
In 4-person carpool	0	±11	0	±1		
In 5- or 6-person carpool	0	±11	0	±1		
In 7-or-more-person carpool	0	±11	5	±		
➤ Public transportation (excluding taxicab):	0	±11	0	±1		
Bus	0	±11	0	±1		
Subway or elevated rail	0	±11	0	±1		
Long-distance train or commuter rail	0	±11	0	±1		
Light rail, streetcar or trolley (carro público in Puerto Rico)	0	±11	0	±1		
Ferryboat	0	±11	0	±1		
Taxicab	0	±11	0	±1		
Motorcycle	0	±11	9	±1		
Bicycle	0	±11	0	±1		

ATTACHMENT C

Projected Bicycle Average Daily Traffic

Projected Bicycle Average Daily Traffic

	Zip Code 61537 (Henry)	Zip Code 61336 (East side)	Zip Codes 61537 / 61336				
			COMBINED				
Projected 2045 ADT	2900	2900	2900				
Total Commuters	1217	233	1450				
Bicycle Commuters	0	0	0				
Bicycle Travel Factor*			0.000000				
Projected Bicycle ADT			0				
*Bicvcle travel factor = Bicvcle Commuters/Total Commuters							

ATTACHMENT D

Bicycle Facility Selection Table (BDE Manual Figure 17-2.A)

	Type and Width of Bicycle Accommodation 11, 27				
Roadway Characteristics 8/	Paved Shoulder	Wider Outside Lane	Bicycle Lane including Buffers	One-way Separated Bicycle Lane ^{4, 5/}	
Rural Roadway Two-Lane, ≤ 40 mph					
Design Year ADT < 2,900	3 ft (0.9 m) e/	14 ft (4.2 m) 7/			
Design Year ADT 2,900 - 8,000	4 ft (1.2 m)				
Design Year ADT > 8,000	5 ft (1.8 m)				
Rural Roadway Two-Lane, ≥ 45 mph					
Design Year ADT < 2,750	3 ft (0.9 m) e/	_			
Design Year ADT 2,750 - 5,000	4 ft (1.2 m)				
Design Year ADT 5,001 - 10,000	5 ft (1.5 m)				
Design Year ADT > 10,000	6 ft (1.8 m)				
Rural Roadway Multilane, All Speeds					
Design Year ADT < 12,000	6 ft (1.8 m)				
Design Year ADT ≥ 12,000	8 ft (2.4 m)				
Urban Roadway Two-Lane, <30 mph					
Design Year ADT < 2,900		14 ft (4.3 m) ⁷⁷	5 ft (1.5 m)		
Design Year ADT 2,900 - 4,000		1410(4.011)	5ft (1.5 m)		
Design Year ADT > 4,000			6 ft (1.8 m)		
Urban Roadway Two-Lane, 30-35 mph			011(110111)		
Design Year ADT < 2,900			5 ft (1.5 m)		
Design Year ADT 2,900 - 4,000			6 ft (1.8 m)	7 ft (2.1 m)	
Design Year ADT 4,001 – 9,500			7 ft (2.1 m)	7 ft (2.1 m)	
Design Year ADT > 9,500			8 ft (2.4 m)	7 ft (2.1 m)	
Urban Roadway Two-Lane, 40 mph			011(2.4111)	710(2.1111)	
Design Year ADT < 3,500			6 ft (1.8 m)	7 ft (2.1 m)	
Design Year ADT 3,500 – 7,700			7 ft (2.1 m)	7 ft (2.1 m)	
Design Year ADT > 7,700			8 ft (2.4 m)	7 ft (2.1 m)	
Suburban Roadway Two-Lane, 40-45 mph			011 (2.4111)	710(2.1111)	
Design Year ADT < 6,500	6 ft (1.8 m)			7 ft (2.1 m)	
Design Year ADT ≥ 6,500	8 ft (2.4 m)			7 ft (2.1 m)	
Urban Roadway Four-Lane, <30 mph	011 (2.4111)			7 11 (2.1111)	
Design Year ADT < 5,800		14 ft (4.3 m) ^{7/}	5 ft (1.5 m)		
Design Year ADT 5,800 - 8,000		1411 (4.5111)	5ft (1.5 m)		
Design Year ADT > 8,000			6 ft (1.8 m)		
Urban Roadway Four-Lane, 30-35 mph			611 (1.0111)		
			E 64 / 4 E mm		
Design Year ADT < 5,800		 	5ft (1.5 m)	7 ft /2 4 m)	
Design Year ADT 5,801 – 8,000		-	6ft (1.8 m)	7 ft (2.1 m)	
Design Year ADT 8,001 – 19,000			7 ft (2.1 m)	7 ft (2.1 m)	
Design Year ADT > 19,000			8 ft (2.4 m)	7 ft (2.1 m)	
Urban Roadway Four-Lane, 40 mph			C 51 (4 C)	744 (0.4)	
Design Year ADT < 7,000			6ft (1.8 m)	7 ft (2.1 m)	
Design Year ADT 7,000 – 15,400			7 ft (2.1 m)	7 ft (2.1 m)	
Design Year ADT > 15,400			8 ft (2.4 m)	7 ft (2.1 m)	
Suburban Roadway Four-Lane, 40-45 mph					
Design Year ADT < 13,000	6 ft (1.8 m)			7 ft (2.1 m)	
Design Year ADT ≥ 13,000	8 ft (2.4 m)			7 ft (2.1 m)	

BICYCLE FACILITY SELECTION TABLE FIGURE 17-2.A (1 of 2)

Notes:

- 1/ A shared use path adjacent to the roadway (i.e., a side path) is an option that fulfils accommodation requirements in most situations. A side path can be selected whenever it is locally supported and the locals agree to maintain it. Two-way side paths shall be a minimum of 10 ft (3.0 m) wide.
- 2/ All widths shown are considered minimums for typical design situations. Wider facilities can be provided. Project-level assessments of highest-and-best facilities may also affect widths provided.
- 3/ Bicycle lane widths are measured from the outside lane line to the face of curb or edge of parking lane. Bicycle lane widths of 5 to 6 ft may be buffered; widths greater than 6 ft must be buffered. Buffer striping is included in the bicycle lane widths shown.
- 4/ One-way separated bicycle lane width shown is the minimum clear width between vertical features and allows bicycle passing. Additional width is needed for vertical elements such as raised curbs, tubular markers with striped buffer, or parking lanes. Each jurisdiction may identify larger minimum clear width restrictions based on maintenance requirements.
- 5/ As an alternate to a one-way SBL, a two-way SBL of a minimum 8 ft (2.4 m) clear width can be provided on one side of the roadway. Additional width is needed for vertical elements.
- 6/ This value assumes no rumble strips are present. If rumble strips will be installed, utilize Standard 642006 and increase the paved shoulder width to 4 ft (1.2 m) to maintain the required 3 ft (0.9 m) clear width for bicycles.
- 7/ Truck (Single Unit + Multi-Unit) volumes should be less than 3% of ADT in order to select a Wider Outside Lane accommodation. Refer to Figure 17-2.C for measurement of the Wider Outside Lane.
- 8/ Refer to Section 17-2.03. Determine Project Context in the Scoping Phase. Speeds listed refer to posted speed limits and are assumed consistent with the 85th percentile speed.

BICYCLE FACILITY SELECTION TABLE

Figure 17-2.A (2 of 2)

ATTACHMENT E

Bicycle Level of Service (BDE 1703)

Four-Foot Shoulder Accommodation

SHOULDER ACCOMMODATION 2016 Highway Capacity Manual (6th Ed Volume 2 - Chapter 15	1)	USER INPUT	CONTRACT ROUTE SECTION COUNTY ADT DATE	68F09 FAP 653 (IL (104B-D)BR Marshall/Pt 2,900 1/31/2022	
Outside Lane Width (ft)	WoL	12			
Paved Shoulder Width (ft)	W_s	4			
Hourly directional vehicle volume = 55% of future DHV; DHV = 10% of ADT	v	160	2900	ADT	
Number of thru lanes each direction	N	100	2900	ADI	
Percent Trucks (SU + MU) (decimal)	T	0.05			
Posted Speed Limit	Sp	45			
Percent with on-highway parking	%OHP	0			
Pavement Rating (CRS)	Р	5	FHWA Rating	2.75	
PHF = Peak Hour Factor Use 0.9 for rural roadways Use 0.92 for urban roadways	PHF	0.9			
CALCULATE DIRECTIONAL FLOW RATE IN THE OUTSIDE LANE	V _{oL}	177.78			
CALCULATE EFFECTIVE WIDTH	5				
Effective width as a function of traffic					
volume	W_{\vee}	19.2			
Find Effective Width	$W_{\rm e}$	23.2		BLOS Score	Grade
	8		•	<= 1.5	Α
CALCULATE SPEED FACTOR		-	ĭ	> 1.5 - 2.5	В
Effective speed factor	S _t	4.42		> 2.5 - 3.5	С
			** 	> 3.5 - 4.5	D
BICYCLE LEVEL OF SERVICE (BLOS)	Score	3.67		> 4.5 - 5.5	E
	Grade	D		> 5.5	F

Formula Cells - no input by user

Printed 1/31/2022 BDE 1703 (10/06/21)

Six-Foot Shoulder Accommodation

SHOULDER ACCOMMODATION 2016 Highway Capacity Manual (6th Ed Volume 2 - Chapter 15	I)	USER INPUT	CONTRACT ROUTE SECTION COUNTY ADT DATE	68F09 FAP 653 (IL (104B-D)BR Marshall/Pu 2,900 1/31/2022	
Outside Lane Width (ft)	WoL	12	1		
Paved Shoulder Width (ft)	Ws	6			
Hourly directional vehicle volume = 55% of future DHV; DHV = 10% of	.,	160	2000		
ADT Number of thru lanes each direction	V N	160	2900	ADT	
Percent Trucks (SU + MU) (decimal)	T	0.05			
Posted Speed Limit	S _p	45			
Percent with on-highway parking	%OHP	0			
Pavement Rating (CRS)	Р	5	FHWA Rating	2.75	
PHF = Peak Hour Factor Use 0.9 for rural roadways Use 0.92 for urban roadways	PHF	0.9			
CALCULATE DIRECTIONAL FLOW RATE IN THE OUTSIDE LANE	V _{oL}	177.78			
CALCULATE EFFECTIVE WIDTH					
Effective width as a function of traffic					
volume	$W_{\!\scriptscriptstyle ee}$	21.6			
Find Effective Width	$W_{\rm e}$	27.6		BLOS Score	Grade
	8	•	•	<= 1.5	Α
CALCULATE SPEED FACTOR		-	ī	> 1.5 - 2.5	В
Effective speed factor	S _t	4.42		> 2.5 - 3.5	С
1	I Const		- Î	> 3.5 - 4.5	D
BICYCLE LEVEL OF SERVICE (BLOS)	Score	2.55		> 4.5 - 5.5	E
	Grade	С	l	> 5.5	F

Formula Cells - no input by user

Printed 1/31/2022 BDE 1703 (10/06/21)

Eight-Foot Shoulder Accommodation

SHOULDER ACCOMMODATION		CONTRACT	68F09		
2016 Highway Capacity Manual (6th E		ROUTE	FAP 653 (IL	18)	
Volume 2 - Chapter 15			SECTION	(104B-D)BR	V.
			COUNTY	Marshall/Po	utnam
			ADT	2,900	
			DATE	1/31/2022	
		USER INPUT			
Outside Lane Width (ft)	WoL	12			
Paved Shoulder Width (ft)	Ws	8			
Hourly directional vehicle volume					
= 55% of future DHV; DHV = 10% of					
ADT	V	160	2900	ADT	
Number of thru lanes each direction	N	1	1		
Percent Trucks (SU + MU) (decimal)	Т	0.05]		
Posted Speed Limit	Sp	45	1		
Percent with on-highway parking	%OHP	0			
Pavement Rating (CRS)	Р	5	FHWA Rating	2.75	
PHF = Peak Hour Factor					
Use 0.9 for rural roadways					
Use 0.92 for urban roadways	PHF	0.9			
			1		
CALCULATE DIRECTIONAL FLOW					
RATE IN THE OUTSIDE LANE	V _{OL}	177.78			
	-		=		
CALCULATE EFFECTIVE WIDTH			ř		
Effective width as a function of traffic					
volume	W _v	24			
Find Effective Width	W _e	32		BLOS Score	Grade
	N		-	<= 1.5	Α
CALCULATE SPEED FACTOR				> 1.5 - 2.5	В
Effective speed factor	S _t	4.42		> 2.5 - 3.5	С
			-	> 3.5 - 4.5	D
BICYCLE LEVEL OF SERVICE (BLOS)	Score	1.24		> 4.5 - 5.5	E
	Grade	Α		> 5.5	F

Formula Cells - no input by user

Printed 1/31/2022 BDE 1703 (10/06/21)

APPENDIX 8

Bridge Type Screening Memo





IL-18 over Illinois River Bridge Replacement Bridge Type Evaluation Henry, Illinois, Marshall and Putnam Counties

August 2022

TABLE OF CONTENTS

T	ABLE OF CONTENTS	
	Executive Summary	1
	Introduction	2
	Existing Bridge	3
	Selection Criteria	3
	Geometric Requirements	3
	Span Length and Vertical Clearance	3
	Roadway Elements	3
	Alignment	3
	Cost	4
	Constructability	4
	Maintainability	4
	Visual Impact	4
	Potential Bridge Types	5
	Option 1: Steel Plate Girder Bridge	5
	Option 2: Single Span Truss Bridge	6
	Option 3: Single Span Arch Bridge	7
	Evaluation and Recommendations	7
	First Cost (30%)	7
	Maintenance (25%)	7
	Redundancy (25%)	8
	Profile (15%)	8
	Public Input: (5%)	8
	Result	9
	References	10
	Attachment 1	11
	Attachment 2	13

Executive Summary

The Illinois Department of Transportation is evaluating bridge replacement alternatives for the existing IL-18 bridge over the Illinois River at Henry. The existing bridge is multiple simply supported truss spans with steel stringer approaches. A new bridge would feature two wider lanes and shoulders, with slightly increased horizontal and vertical clearance requirements on the main navigation span. Modern design policy favors shallower approach grades than the 5% found on the existing bridge. Alignment studies have identified two alignments at the immediate upstream (Corridor #3) and downstream (Corridor #5) as candidates for the preferred alternate. The present study investigates feasible structure types for the main navigation span. The pros and cons of each type are discussed and scored based on various criteria, including cost, maintenance, performance, and public input.

Per the US Coast Guard, a horizontal clearance of 360' is required on the main span. An increase of 2.5' over the existing vertical clearance is also required. These increases, coupled with policy preference for flatter approach slopes, raise the matter of structure depth and its effect on roadway profile as potential discriminators among bridge type. Structural depth will also affect the total length of the bridge and the amount of embankment walls in the town, which not only affect the cost of the bridge, but also impact the community. The conventional priorities of first cost, maintainability, and redundancy are also discussed. Final scores and a ranking are based on a weighted sum of all screening criteria. The results indicate that a haunched continuous plate girder bridge is the best bridge type for the main river spans of the IL-18 over Illinois River bridge at Henry.

Introduction

Illinois DOT is performing Phase I engineering for replacement of the existing IL-18 bridge over the Illinois River at Henry, IL, Marshall and Putnam counties. The basis for replacement is discussed in the Bridge Condition Report and the Alternatives Carried Forward memoranda. The new candidate alignments that remain under consideration are "Corridor 3" and "Corridor 5", see Figure 1. These lie parallel to existing, offset 50' to 100' upstream or downstream, respectively. On the east (south), the new bridge will touch down and tie back into the existing IL 18 alignment at some convenient location west of the Sandy Creek bridge and IL-26 intersection. On the west (north), the alignment will touch down and tie back into School Street (existing IL-18) with as little disruption to property and street grid as is reasonably possible.

This memorandum evaluates feasible structure types and establishes a recommended bridge type.




FIGURE 1: CORRIDOR 3 (IMMEDIATELY UPSTREAM OF EXISTING) AND CORRIDOR 5 (IMMEDIATELY DOWNSTREAM OF EXISTING).

Existing Bridge

The existing bridge was constructed in 1934 and is 88 years old in 2022. It carries two 11'-4" lanes with no shoulders. The main river bridge consists of six (6) simply supported through-truss structures, with a main span of 364' above a navigation channel, see Figure 2. It provides 59.2 ft vertical clearance above pool stage (USACE, 2013). To provide this vertical clearance, the roadway has a 5% grade between the main span and the intersection with Front Street in Henry.




FIGURE 2: EXISTING BRIDGE

Selection Criteria

Geometric Requirements

SPAN LENGTH AND VERTICAL CLEARANCE

In the case of a navigable waterway such as the Illinois River at Henry, the US Coast Guard is charged with setting and enforcing the accommodations which bridge must meet for the sake of commercial navigation. The clearances on the existing Henry bridge are 350 ft horizontally, and 59.2 ft vertically (referenced to normal pool). For the new structure, for alignments close in and parallel to the existing, the USCG has established requirements of 358 ft horizontally, and 61.7 ft vertically (USCG, 2022). The horizontal span in particular conditions the type of bridge which is normally found economical. The depth of some structures increases as horizontal span increases. The depth of other structure types can be insensitive to increases in span length.

ROADWAY ELEMENTS

The needs of vehicular traffic, including agricultural and truck traffic, dictate desirable width of the bridge, as well as the roadway grades leading up to and down from the bridge. The face-to-face width between bridge rails has been established as 40 ft, providing for one 12 ft lane and one 8 ft shoulder in each direction. Some bridge types are sensitive to this width dimension, with structure depth increasing as width increases. Others are not.

Modern design policy for a state route such as IL-18 in this mixed rural/urban setting targets a 3% grade on the roadway. Flattening the roadway grades from the existing 5% to 3%, while trying to increase the vertical clearance for navigation, while trying to maintain connection to the Henry street grid, are conflicting objectives. The desire to provide a balanced design which minimizes community impacts while providing safe and efficient operations on IL 18 is an aspect of project development. How structure type affects the depth of structure below the roadway will impact the roadway grades. It also determines how far the bridge must run out before returning to grade (total bridge length).

ALIGNMENT

The location for the new bridge, the alignment on which the new IL-18 will be constructed, has been the subject of study and community input comprising the Phase I Engineering process. The alignments which best meet the project's purpose and need and the priorities of the project stakeholders have been established to be parallel and just offset from the existing bridge, either upstream or downstream. The choice between either an upstream or downstream option does

not affect which structure type would be preferred; neither site is distinguished with regard to favorable or unfavorable bridge types.

Cost

The state must consider initial cost, to construct the bridge, and ongoing life-cycle cost to maintain the bridge, in respect of their mission "... to provide safe, cost-effective transportation for Illinois in ways that enhance quality of life, promote economic prosperity, and demonstrate respect for our environment."

Constructability

Simplicity and familiarity of construction type lower construction risk, construction time, and construction cost. Simpler, more familiar types of construction are preferred over types whose erection is complex, requires novel methods and equipment, or requires technical sophistication.

Maintainability

Bridges must sustain many decades of repeated cycles of heavy loading, in full exposure to the elements of weather and chemical attack associated with snow and ice removal. Bridges must be inspected every 2 years and defects promptly repaired. Bridge types which are more fault tolerant are preferred. So-called fracture critical bridge types, in which loss of a single member can reasonably precipitate complete loss of the bridge, are not preferred.

Coatings on steel protected from direct exposure to the elements have a life of 20 to 25 years, before re-coating is required. Coatings with more direct exposure to moisture, weather, and traffic require more frequent maintenance. Bridge types which protect the primary structural elements are preferred.

Reinforced concrete bridge decks (driving surface) are common to virtually all bridge types. Decks typically experience a major structural repair cycle between 20 and 30 years of life and are typically completely removed and replaced between 40 and 50 years of life. The ease with which deck replacement can be carried out is a factor in determining preference for one bridge type over another.

Visual Impact

Aesthetic quality, or visual impact, is not typically a factor that is considered in selecting a bridge type. Where very long spans are required (the Golden Gate in San Francisco Bay, the East and Hudson Rivers in New York) or where topographic constraints are severe (Hoover Dam in Nevada), visually arresting and so-called iconic structures do arise. Modern crossings of inland waterways around the Midwest do not typically have the kinds of span length or terrain accommodation that leads to such structures.

Economical, constructible bridge types have also changed in the generations since the last generation of Illinois River bridges was constructed. In the 1930's the availability of material, and the ability to fabricate, transport, and erect it, required the use of truss bridge technology to achieve spans of 250' to 350' as in Henry. Out of the river, where conditions allowed shorter spans, the original designers reverted to girder type bridges.

Where investment in aesthetic enhancement is determined consistent with the mission of providing a safe, cost-effective transportation system that respects the environment, such enhancements normally take the form of landscaping, grading, and ornamentation of large surfaces through texture, color, and lighting. Selection of structure type is a primarily function of engineering and cost requirements. Due to community interest, visual aesthetics were considered as a possible tie-breaker should multiple bridge types be nearly equal after considering other categories.

Potential Bridge Types

All roadway bridges may fall into one of the four basic types: girder, truss, arch and cable supported. Some bridge types and their sub-variations were quickly screened and excluded from further comparison. These are:

- Simply supported girder bridge: extremely inefficient and impractical for a span range of 400 ft.
- Deck arch bridge: impractical due to the occupation of the navigational clearance by the arch.
- Cable supported bridges, including cable-stayed bridge and suspension bridge: They are the most complex types
 of bridges, requiring specialized erecting and prestressing equipment in construction, and specialized inspection
 devices in service. Cable supported structures behave quite differently from other bridge types and are not well
 suited to span lengths in the low hundreds of feet. The expense and complexity of cable supported bridges are
 normally only accepted as spans approach or exceed 1000 ft, where the challenges of girder, arch or truss types
 exceed those of cable supported types.

As evidenced by recent truss replacements at Morris, Seneca, Utica, Spring Valley, Beardstown (in design) and Florence (in design), girder bridge technology has repeatedly proven to be an economical and constructible solution in the 350 ft to 400 ft span range on the Illinois River. On the Mississippi, at the Chain of Rocks Canal, IDOT recently replaced an original truss bridge with a (haunched) girder span of 490 ft. This is near to the upper limit of span which can be accomplished economically and practically with girder technology.

On the Illinois River at Peoria and Meredosia and the Mississippi River at Savanna, arch type structures have also been selected. These are primarily a function of the large horizontal clearance requirements established by the USCG on those sites. The Meredosia site shares some of the concerns for road grade and reconnection to town street grid which is immediately off the riverbank.

Truss bridges, which were a common and optimal solution for long spans from the early to mid-1900's, are built less frequently now. The I-72 bridge over the Mississippi at Hannibal is one of the few regional examples of a recent truss span. The state of lowa is designing a truss for the replacement of a 700 ft span over the Mississippi at Lansing.

Through-type structures such as truss and arch can be made relatively shallow in terms of depth below the roadway. Their depths are more controlled by the transverse spacing associated with width of the road, rather than the length of the span between piers in the river. Girder bridges, in contrast, must get deeper as the length of the span increases. In the case of the Meredosia bridge, the selection of arch over girder type mitigated the problem of IL-104 approaching town from a higher elevation but could not eliminate the effect of tall embankments nor the requirement for retaining walls extending into town.

For the Henry bridge with a span of just under 400 ft, but with profile concerns for touching back down in town, the continuous-girder and the through-type bridges (truss and arch) are considered in the following.

Option 1: Steel Plate Girder Bridge

This option uses the longitudinal steel girders as the main force-resisting structure. This option can be refined to two sub-options. Option 1A: Constant depth plate girder, see Figure 3 (a). Option 1B: Haunched plate girder, see Figure 3 (b). For Option 1A, the minimum depth of the steel girder is about 10.5 ft, total structural depth is about 11.75 ft. The existing structure depth is about 6 ft. USCG requirements lead to low steel needing to increase by 2.5 ft, from elevation 499.2 to elevation 501.7. Considering the existing structural depth of 6', the new profile for a constant depth girder is 8.25 ft higher than existing (11.75-6.0+2.5). For the haunched girder of Option 1B, the steel depth at midspan can be reduced to 8.0 ft with a total structure depth 9.25'. The new profile for a haunched girder could be 5.75 ft higher than existing.

Since the steel plate girder bridge is the most common type of bridge, it is used as a reference to compare with other options. Additional details are estimated for this option as the basis of this comparison.

Bridge length: The existing bridge is about 1718 ft long with 5% grades. The tangent slope is 486 ft long to the west and 869 ft to the east. With 8.25 ft profile raise and 4%-3% desired slopes, the total length of the bridge will increase. Considering how the west bank in the town is going up slope as the bridge lengthens, and that we can increase the embankment depth at the west abutment, the anticipated total bridge length for Option 1A is about 2050' (back-to-back of abutments). This is 332 ft longer than the existing bridge. For Option 1B, the total length would be about 1906 ft, or 188 ft longer than existing, but 144 ft shorter than Option 1A.

Bridge cost: Based on investigation of recent bid prices of similar bridges with long girder spans and approach spans over major rivers, the approach spans are estimated to cost \$250/SF. The long-span units are estimated to cost at \$500/SF for Option 1A, and \$515/SF for Option 1B (3% increase). The resulting total bridge construction costs are \$32.8 M for Option 1A, and \$31.9 M for Option 1B. The reduced overall length covers the slight increase in cost for the long-span unit. At the west abutment, both Option 1A and Option 1B land 96 ft beyond current abutment. The embankment height behind west abutment is 14'-8" at Option 1A and 10'-5" at Option 1B.




FIGURE 3: STEEL PLATE GIRDER BRIDGES, OPTION 1(A) AND 1(B).

Option 2: Single Span Truss Bridge

The challenge presented by a long navigation span and the desire to limit the slope and grade raise of the road can be met by using a truss as a single span at the navigation opening, see Figure 4. The approaches, with less stringent horizontal and vertical clearance requirements are efficiently developed as girder spans. Using modern high strength steels and particular floor framing details, the total depth below the roadway can be held similar to existing, although the new bridge will be almost twice as wide as existing. Therefore, the main span profile has a 2.5 ft rise associated with the navigation requirement. The approach spans can use the same structural depth of the main span for span lengths ranging from 150 to 200 ft.

Due to a dip in the ground elevation near the new east abutment, the further lowering of the profile does not reduce the total bridge length very much. The bridge is estimated 1878 ft long, which is 160 ft longer than the existing, and 172 ft shorter than Option 1A. Building the main span truss is about 50% more expensive comparing to the girder bridge based on review of costs for similar truss bridges. By limiting the expensive structure type to the single navigation span, and shortening the bridge by lowering the profile, the initial cost to construct this bridge is about \$31.7 M, which is in the same range as the girder bridges. Comparing with Option 1A, the bridge profile is about 6 ft lower. However, this improvement is not enough to eliminate the impact at the Front St. An 8-ft tall embankment is still needed at Front St.




FIGURE 4: OPTION 2, TRUSS BRIDGE

Option 3: Single Span Arch Bridge

The main navigation channel can also be spanned by a single tied arch structure, with girder approach spans, see Figure 5. As mentioned above, the depth of structure below the roadway is controlled by the floor beam. For a face-to-face roadway width of 40 ft, the floor beams will span about 50 ft and can be designed with a depth of 4 ft. Similar to the floor framing of the existing bridge, the longitudinal stringers can be framed between floor beams without taking extra structural depth. The governing total structural depth can be the same as the truss bridge, therefore only 2.5 ft of profile raise is needed, for the navigation accommodation. The arch bridge will be the same length as the truss option. Comparing to Option 1A, the main span will cost 75% more than a girder bridge based on the bid price of some similar arch bridges. But the side spans will cost less. The total construction cost of the bridge is expected to be about \$33.8 M, which is \$1 M more than Option 1A, and \$2 M more than Option 1B and Option 2.




FIGURE 5: OPTION 3, TIED ARCH BRIDGE

Evaluation and Recommendations

To do a closer comparison among the above three options, the Selection Criteria categories are assigned weighting factors, and scores for each bridge type in each category are assigned. The weighting factors are selected to reflect IDOT's mission – providing a safe and efficient transportation system and reflect the preference of local people. Those criteria related to IDOT's mission are given higher weights. The pros and cons of each bridge type are considered in establishing the scores. Table 1 summarizes the weights, scores, and ranking.

First Cost (30%)

First cost reflects the initial construction cost; the contract value for a builder to supply the material, equipment, and labor to construct the bridge. A weighting factor of 30% (about 1/3 of the decision) is attached to construction cost. Among the four options, construction costs turn out to be very similar, and are not a strong differentiator. They are all in the neighborhood of \$32M. The haunched girder (Option 1B) and the truss bridge (Option 2) have the lowest, and almost the same initial cost. The constant-depth girder (Option 1A) is about \$1 M higher (3%), and the arch bridge is estimated \$2M higher (6%). Based on the relative lack of differentiation, the options are scored as 5 (arch and constant depth girder) or 6 (slight cost preference for haunched girder or truss)

Maintenance (25%)

The maintenance score reflects the challenge and cost of keeping the bridge inspected and in good working order over the expected bridge life of 75 to 100 years. Inspections, cleaning, painting, patching, and eventual replacement of the concrete deck are reflected in maintenance, as are the associated interruptions to traffic. The girder bridge options (Option 1A and 1B) are strongly preferred over the through-type structure options in this context. Girder bridges do not have structure above the deck; the main structural elements, those which require painting and inspection are tucked under the concrete deck. Girder bridges are also easy to widen in the future, if traffic demands should ever require that. In contrast, both truss and arch bridges have overhead structure, exposed to water and salt spray, exposed to vehicle and debris damage, and requiring greater traffic disruption to inspect and repair. It is also not practical to widen a truss or arch type bridge in the future. The life-long implications of the maintenance category are of similar priority to the redundancy category (below) and almost as important as the first cost category. A weight of 25% is assigned to the maintenance category. The girder options are scored as 10 (highly preferred), and the through girder structures are scored as 4 (not preferred)

Redundancy (25%)

Redundancy reflects the fault tolerance of a bridge. Flaws can arise in design, materials, or construction. Flaws can be introduced over time as a result of corrosion, collision, and repetitive loading of heavy trucks. Steel girders are a common, well-understood, and relatively low-tech structural system. The assembly of (typically) 6 girder lines for a bridge like this makes a system that is intrinsically redundant by normal design without additional cost. A flaw or damage introduced to any one girder is not considered capable of causing total loss of a span. Truss and arch bridges, on the other hand, are not intrinsically redundant. The lower chord (truss) or tie beam (arch) are defined as Fracture Critical Members (FCM). Loss of any part of an FCM can results in total loss of a span. The safety of bridges with FCM must be addressed by using more expensive materials, fabrication type, and taking on a higher level of inspection and maintenance over the life of the structure. The use of FCM's always attracts scrutiny and requires justification to the State DOT and to the Federal Highway Administration.

A weight of 25% is assigned to Redundancy, making it of similar importance to life-long maintenance, and combined with maintenance making it more important than first cost. The girder type bridges are highly preferred in the redundancy category and scored as 10. The fracture critical through structure types are scored as 4. Taken together, maintainability and redundancy are considerably more important than the first cost category.

Profile (15%)

Profile is important for the cost (bridge length), design policy (grade steepness), and the impact on tying the new roadway back to the existing Henry street grid. For these reasons, the Structure Depth (or Profile) is given a relatively high weight of 15%. The constant-depth girder option (1A) requires the highest roadway profile making it the least desirable. The through structures of truss and arch allow the lowest roadway profile, making them the most desirable in this category. The profile improvements associated with the shallow depth through structures are not enough to prevent the disruption of Front St at IL-18 in the proposed condition. They will, however, mitigate the visual and ROW impacts of the required grade raise. The options are thus differentiated with assigned scores ranging from 10 to 8 to 6, most desirable to least.

Public Input: (5%)

Public Input represents any and all sentiments which might be expressed in public comments and through the forum of Community Advisory Group (CAG) meetings. This could, for example, be a simple aesthetic preference between structure types. It could, for example, be a judgement on whether one structure type or another responds more favorably to the project Purpose and Need in their eyes. A weight (5%) is assigned to this category. This reflects the much larger priority that the Owner (the State and its stewardship of federal dollars) must put on the categories of cost, maintenance, and redundancy. It also reflects the fact that CAG interest in limiting the visual and street grid impacts of the raised and widened road is also partially captured in the "Profile" category. The 5% weight reflects this category's role as a potential tie-breaker, as opposed to a primary driver.

At CAG Meeting 5, a preview of these four bridge types and their evaluations was presented. Feedback was consistent with feedback received at prior meeting in which the topic of bridge type has arisen. Many members of the CAG expressed concerns that the girder type bridges lack the visual drama of a through type structure, do not serve as a distinguishing landmark, and do little to attract attention to Henry. Several voices in the community express the opinion that a truss or an arch type structure is more preferable, for its monumental appearance and its potential to enhance the view of the river and river front. The sole written comment received in response to the preview presentation is along these lines, and is reproduced as Attachment 1.

On the other hand, comments have also been voiced in CAG meetings to the effect that a priority for the replacement bridge should be speed; the existing crossing should be upgraded via replacement as quickly as possible. If a girder type bridge results in rapid approval, and a through type structure results in protracted justification and reevaluations and lobbying efforts, a girder type bridge would be preferred from that viewpoint. It was also noted

during CAG Meeting 5 that the girder type bridge results in the longer side spans, effectively reducing the number of piers in the waterway which could be considered a benefit or safety improvement for users of the river. The absence of structural members overhead that is achieved by the girder type bridge was also noted as possible benefit to the high and wide loads which arise with agricultural implement traffic.

Although no quantitative ranking or voting was conducted, CAG input to the four structure types has been assigned as 3 (Constant Depth Girder, least preferred), 5 (Haunched Girder), 8 (Arch Bridge), and 9 (Truss, most preferred). Per the discussion above, it is debatable whether the full CAG judges a truss this much more preferred than a girder; these selections serve, however, to show that even with significant preference expressed for through structure types, they are not able to rise above the other factors favoring girder type bridges.

Result

The category scores of each bridge type are combined in a weighted sum to create a single weighted score value for each bridge Type in Table 1.

Constr. First Maint. Redun Profile **Public** Weighted Rank Option Type Sketch Cost Cost dancy Input Total 0.30 0.25 Weight 0.25 0.15 0.05 10 Plate 32.8 M 5 10 10 6 3 7.6 2 1A Girder Haunched 1B 31.9 M 6 10 10 8 5 8.3 1 Girder 2 31.7 M 4 4 10 9 5.8 3 Truss 4 10 3 33.8 M 5 4 8 5.4 4 Tied Arch

Table 1: Bridge Type Scoring and Ranking

Note: Score of 10 represents most favored, 1 represents least desirable.

Despite the relatively small differentiation among structure types based on first cost, overall the categories, weights, and scores combine to present a clear picture of the most preferred option. For their advantage in cost, maintenance and redundancy, the girder bridge types are preferred to the through structure types in this span range (350 ft to 400 ft). Because of the relative importance of profile in this project, the modest increase in complexity associated with a haunched type girder is preferred by more than half a point over the constant depth girder. The ordered final rankings are:

Bridge Type	Score (out of 10)
Haunched Girder	8.3
Constant Depth Girder	7.6
Truss	5.8
Arch	5.4

Development of the new IL-18 river bridge, along either alignment 3 or 5, should proceed based on use of a haunched plate girder navigation span.

References

US Army Corp of Engineers (2013). Illinois Waterway Navigation Charts Grafton, IL to Lake Michigan at Chicago and Calumet Harbors. Mississippi Valley Division, Great Lakes & Ohio River Division.

US Coast Guard (2022). Electronic letter dated 3/1/22 from Eric Washburn (USCG) to Travis Wallenfang (IDOT D4).

Attachment 1

Community Advisory Group Comment: Bridge Type Screening Presentation

IL 18 River Bridge Project IDOT – District 4 401 Main Peoria, IL 61602

I.D.O.T. Received

JUL 1 8 2.22

Region 3 / District 4

401 Main S

To whom it may concern:

Please find my 'public input' for the bridge types presented.

- Constant depth girder red
- Haunched girder red
- Truss yellow
- Arch green

Aesthetics is important to this river town. This was clearly communicated from Day 1. We will live with, and look at, this bridge long after the IL 18 River Bridge Team has come and gone. While we will live with town, we are actively pursuing multiple initiatives to enhance the appeal of our riverside community. This new bridge has the potential to be a cornerstone piece of the reimagining of our hometown.

I feel as if this entire process -- the "bringing us along", if you will -- including the painstaking bureaucracy culminated into the ultimate disappointment during the last CAG meeting. To deliver the message, and try to "sell" us, the very type of bridge that we stated on Day 1 that we didn't want made this entire process feel like a colossal waste of time as well as personally insulting.

A plain-Jane vanilla girder bridge has its place. Locations that are simply a connection between two pieces of land with no community or personality at play fit this use-case. However, a community river town where the bridge is part of the history and heritage is not a use-case for such a structure. To attempt to use maintenance and redundancy categories as just-cause for not building a more aesthetically pleasing structure was a poorly delivered excuse. Certainly, building an appealing and memorable bridge is within the capability of IDOT, as evidenced by the many communities that have them. While perhaps not 'necessitated' by the technical requirements of the structure, it would be a waste of an opportunity to not grant the city of Henry an aesthetically pleasing bridge when it costs no more or less than the unattractive and forgettable design proposed by IDOT. A new bridge only comes around once in a lifetime so to not take advantage of this moment in time is a true shame. I'm disappointed that the bridge engineer tried to play on the emotions of the audience by citing bridge failures for the design types he knew we would be more in-favor of. To suggest that IDOT cannot build a beautiful <u>and</u> safe bridge is nonsense.


There you have it -- my two cents ... which is apparently worth only 5%.


An anonymous CAG member


CC: Jeff Bergfeld, Mayor of Henry


Attachment 2

Plan and Profile Comparison Exhibits: Girder, Haunched Girder, Truss, Tied Arch












APPENDIX 9


Type Size and Location Plan



8/6/2025 12:22:17 AM







STATE OF ILLINOIS

DEPARTMENT OF TRANSPORTATION

653

SHEET 4 OF 4 SHEETS

104B-D

MARSHALL

CONTRACT NO. 68F09

REVISED -

REVISED

REVISED

CHECKED - TCU

CHECKED - TCU

DRAWN

6/18/2025 7:08:08 PM

PARSONS

APPENDIX 10

Bridge Condition Report



BRIDGE CONDITION REPORT

Original March 17,2021

Rev 1 November 3, 2021

REGION:	3
DISTRICT:	4
ROUTE:	IL 18
COUNTY:	Marshall (and Putnam)
JOB NUMBER:	P-94-007-20/D-94-041-19
STRUCTURE NUMBER:	062-0036
LOCATION:	IL-18 over Illinois River at Henry, IL



PREPARED BY:	Todd Ude, Parsons
DATE INSPECTED:	The bridge is inspected annually by IDOT forces. Most recent inspection took place 4/5/2021. This BCR is based on most recent NBIS report document, dated 4/20/2020, and an underwater inspection report dated 10/16/2018.
PROPOSED LETTING DATE:	2025



TABLE OF CONTENTS

GEOGRAPHICAL & ADMINISTRATIVE DATA	3
Construction / Reconstruction / Repair History	3
PHYSICAL DESCRIPTION OF STRUCTURE	3
FIELD INSPECTION & PHYSICAL EVALUATION	4
Deck	4
Superstructure	4
Substructure	4
Scour/Slope Protection:	4
Inspection History (NBIS Ratings)	4
Geometric, Horizontal & Vertical Clearance / Hydraulic Data	5
Horizontal and Vertical Clearance Through the Structure	5
Horizontal and Vertical Clearance Beneath the Structure	5
Hydraulic Adequacy	5
POTENTIAL SCOPE OF WORK DETERMINATION & ANALYSIS	5
DISCUSSION AND RECOMMENDED SCOPE OF WORK	6
Cost	6
ATTACHMENT A. LOCATION MAP	8
ATTACHMENT B. IDOT MASTER STRUCTURE REPORT	9
ATTACHMENT C. BRIDGE INSPECTION REPORT	12
ATTACHMENT D. TOP AND BOTTOM OF DECK CONDITION SURVEYS	156
ATTACHMENT E. SUBSTRUCTURE CONDITION SURVEYS	156
ATTACHMENT F. COST ESTIMATES	156
ATTACHMENT G. PROPOSED STRUCTURE	156
ATTACHMENT H. STRUCTURE PHOTOS	157
ATTACHMENT I. HYDRAULIC ANALYSIS SUMMARY	163
ATTACHMENT J. PROPOSED PLAN & PROFILE	163
ATTACHMENT K. EXISTING AND PROPOSED ROADWAY CROSS SECTIONS	163
ATTACHMENT L. ABBREVIATED EXISTING PLANS	163



Geographical & Administrative Data

Structure Number:	062-0036
County:	Marshall
Route Carried:	IL 18 (FAS2369)
Feature Crossed:	Illinois River and Cromwell St.
Section:	104B-D
Station:	13+91.88
Roadway Classification:	Minor arterial
Design/Posted Speed:	40 mph design (assumed) / 35 mph posted
ADT (current/design):	2200 (2019) / 3064 (2032)
ADTT (current/design):	4% trucks
DHV:	
Inventory Rating (HS or HL):	0.68 (HS)
Operating Rating (HS or HL):	1.14 (HS)
Sufficiency Rating:	06.5

Construction / Reconstruction / Repair History

The existing bridge was constructed in 1934 as Route SBI-89C, Section 104-B. It will be 87 years old in 2021.

The bridge was reconstructed in 1988 as Route FAS2369, Section 140B-D. In the steel beam spans, the structure was completely replaced except for the piles. Bent caps and abutments were reconstructed, along with the steel beams and concrete deck. Exposed area of piles in the intermediate bents were repaired as required.

In the truss spans, the floor system was completely replaced along with the concrete deck. Cracks and spalls on the truss piers were repaired.

In 2021, the reconstructed work will be 33 years old.

Physical Description of Structure

The bridge is 1,719 ft long, back-to-back of abutments. The cross section is 22'-8" face to face of rails, or two 11'-4" lanes with no shoulders. The main navigation span is a simply supported 364' through truss. To the north are two more simple span through trusses at 202' each. Two steel beam spans of 42' complete the north approach into the town of Henry. To the south of the navigation span are three simple span through trusses of 202' each. Six steel beam spans of 42' complete the south approach. Thus more than three quarters of the structure length consists of the 6 through truss spans. The deck is a conventionally formed and cast 7.5" reinforced concrete slab.

Substructures for the truss spans are a reinforced concrete portal frame on an unreinforced concrete plinth. The plinth rests on a concrete footing with a single mat of reinforcement. Plans from the original construction provided for 25-ton timber piles supporting the footing. For the deepest footings, at the navigation span, plans directed that ordering of material be deferred until excavation and test piling verified a need for them. The as-built condition is unknown. The 42' beam spans are founded on pile bents comprised of driven reinforced concrete piles and a cast-in-place bent cap. The abutments are spill-through concrete pile bents.



The structure is on tangent alignment, and the substructures are not skewed. The longitudinal grade is 5% on both approaches joined by a 600' vertical curve. There is roadway lighting and navigation lighting mounted on the structure.

Field Inspection & Physical Evaluation

Per the current Master Structure Report (Attachment B), the bridge has an inventory rating factor of 0.68 with date of 10/2019. The bridge is currently signed as posted to legal loads only (Photo 1, Attachment H). The following findings are summarized from the 2019 and 2020 NBIS inspection reports performed by IDOT staff.

Deck

The deck is rated 6 (satisfactory) with minor spalls, delamination and map cracking reported.

Superstructure

The superstructure is rated 3. The paint system on both truss and steel stringer approaches is failing; Element 515 for the paint system records 65% in Condition State 1 (sound and protecting steel) and the remaining 35% in Condition State 4 (corrosion with substantial metal loss and perforation). Steel corrosion is advanced and progressing. Section loss up to 39% of truss members cross sections is reported, see e.g., Span 7 at nodes L3 east and west in Table of Deficiencies within the 2020 Inspection Report (Attachment C). Losses of truss floorbeam bottom flange sections of up to 24% are reported.

Substructure

The substructure is rated 4 (poor), indicating up to 30% loss of concrete reinforcement section and/or up to 30% loss of bearing seat or pile area. Prior concrete repairs have largely failed, and much exposed and corroding reinforcement is visible in the portal frame sections of the truss span piers. Likewise, major areas of exposed corroded reinforcing on the concrete pile bents are apparent. Bents 3 through 6 are identified as up to 3% out of plumb, leaning to the north. The bearing seat areas of truss pier 7 and bent cap 5 (at an expansion joint) have 20% to 25% section loss. According to the 2018 underwater inspection report, concrete below the waterline is in satisfactory condition

SCOUR/SLOPE PROTECTION: Dumped stone riprap armors the north and south embankment cones, which are well removed from the channel at normal flows. The 2018 inspection report does not indicate any specific scour protection on the riverbed at piers 2, 3 and 4. From 2013 to 2018 there was less than a 5' increase in scour depressions at the upstream faces of piers 3 and 4. The least remaining cover over top of footing was about 7', at pier 3, with about 10' from lowest riverbed to bottom of footing. The underwater inspection report presumes the timber piles are present, although the record plans raise the possibility that piles could have been determined unnecessary at time of construction.

Inspection History (NBIS Ratings)

Year	Deck	Super	Sub
2020	6	3	4
2019	6	3	4
2017	7	5	5



Geometric, Horizontal & Vertical Clearance / Hydraulic Data

HORIZONTAL AND VERTICAL CLEARANCE THROUGH THE STRUCTURE

The structure provides 2 lanes 11'-4" each, or 22'-8" face to face of steel rails. Center to center of trusses is 26'-1 ¾". The vertical clearance to portals above the roadway is not known. It is not signed as substandard in the field, but there is evidence of several impact damage to both sway brace portals and main truss members in the 2019 and 2020 NBIS tables of deficiencies and photographs.

In the Structure Summary Report, the bridge railing is appraised as "meets standards", but deck geometry is coded as 2 (intolerable - high priority for replacement).

HORIZONTAL AND VERTICAL CLEARANCE BENEATH THE STRUCTURE

Navigation Channel

According to the US Army Corp Waterway Information Charts, the main span provides 350' horizontal clearance for the navigation channel. The vertical clearance to the normal pool elevation is 59.2'. The US Coast Guard and the Army Corp have reported that navigation interests do not generally report difficulty with this current bridge. However, Coast Guard has signaled that current conventions would require at least 60' vertical clearance to normal pool, and possibly a couple feet more than that.

Existing navigation horizontal and vertical clearances appear satisfactory.

Cromwell Drive

Cromwell Drive is a low-speed local street (driveway) passing beneath the northernmost truss span (right side of Photo 4). Horizontal and vertical clearances are satisfactory.

HYDRAULIC ADEQUACY

The southern approach roadway is prone to occasional flooding (few events per decade) when the Illinois River is in flood. Hydraulic modeling will be conducted in the Phase I project, but the existing bridge is not generally known to be insufficient or inadequate with regard to hydraulic capacity.

Potential Scope of Work Determination & Analysis

In 1988 at age 54 years, the original structure required reconstruction of the approach spans and rehabilitation of the trusses with reconstruction of the floor system. In 2021, the reconstructed decks are in satisfactory condition, but the approach span steel, the truss steel floor system, and the original truss steel are all again in an advancing state of deterioration with section loss. The need for posting the bridge to legal loads only and the need for steel repairs to restore member capacity have begun to arise and will arise with increasing frequency as the structure ages.

The useful life of the 1988 rehabilitations of the concrete substructure has been exhausted. Those repairs are failing, and deterioration of concrete and concrete reinforcement is advancing. Deterioration of reinforced concrete is typical recognized to occur at an increasing rate once chloride ion concentration at the reinforcing steel reaches a critical threshold.

To keep the bridge safe for its design loading, and to mitigate maintenance expenditures over the coming decade, the bridge will require either a 1988-style reconstruction / rehabilitation, or complete replacement.

There are several difficulties with reconstruction / rehabilitation:

1) The objective of major reconstruction / rehabilitation is to return the bridge to a like new condition. The 1988 work secured an additional 33 years of life (so far). This time, the work will be much more involved, given:



- the advanced age and advanced deterioration of the substructures, and
- the need for more widespread intervention on main members and gusset plate connections of the trusses
- 2) A successful reconstruction / rehabilitation would have as its objective a 30 to 40 year life extension. At that time the bridge would be 120 to 125 years old, which is an excessive service life objective for a bridge built in 1934.
- 3) The geometric deficiency of narrow lanes and zero-width shoulders cannot be addressed in any rehabilitation. An existing through truss structure type cannot reasonably be widened.
- 4) An existing through truss cannot reasonably be rehabilitated under traffic, even using a single alternating lane of traffic controlled by signals and flaggers. The bridge would have to be removed from service for several months in connection with any reconstruction / rehabilitation.

A complete structure replacement will allow for development of a low-maintenance, long-life bridge that will meet current roadway geometric criteria for widths, grades, and barriers. Up and down the Illinois River, similar 1930's and '40's era crossings have reached the limit of their economical service lives and have been replaced. Examples from recent decades include IL 47 at Morris, IL 89 at Spring Valley, IL 170 at Seneca, and IL 104 at Meredosia.

Discussion and Recommended Scope of Work

It is evident from the inspection reports, the current legal-loads-only posting, and the ongoing need for concrete and steel repairs that the existing bridge has reached the end of its service life. A major investment in reconstruction and rehabilitation would be required to effect a service life extension, which based on prior experience, is unlikely to provide more than 30 years additional life. This investment would require extended closure of the bridge and leave the structure with the substandard roadway geometry of 11' lanes with zero-width shoulders. A complete structure replacement is recommended.

The Phase I process will generate and evaluate alternatives for the location of a replacement structure. Construction off of the existing alignment would make possible maintenance of traffic on the existing bridge while the new bridge is constructed, at the expense of ROW acquisition. The Phase I process will weigh the pros and cons and costs of replacing on alignment, versus replacing immediately adjacent but tying into the Henry street grid at the same location, versus crossing into Henry on an alternate location. For proximity of bridge to Henry street grid, see Attachment A.

The Phase I process will also establish design criteria for the minor arterial, in particular the merging of rural criteria on the south to the more urban condition on the north. A common choice for rural Illinois River bridge reconstructions has been two 12' lanes with two 8' shoulders, for a 40'-0" face to face width and 43'-2" out-to-out width (42'-10" for the new constant-slope parapet).

It is anticipated that a modern steel girder type bridge will be able to meet the span required by US Coast Guard horizontal clearance requirements. Vertically, the interaction of design criteria for grades, the proximity of the navigation span to the Henry street grid, and the US Coast Guard requirement for vertical clearance could prove challenging to the girder type bridge. The existing crossing employs 5% approach grades and has a structure depth of only about 4'-6". A girder bridge will be significantly deeper, and the vertical clearance requirement may increase. Preliminary indications are that grades between 6% and 7% may be required to keep the bridge tied in near its present touchdown point near the intersection of School St (IL-18) and Front St. The interplay of these factors will be addressed in the Phase I process.

Cost

Refined cost estimates will be developed in conjunction with the replacement structure type study and TSL development within the Phase I process for bridge replacement. In 2015, IDOT replaced a similar truss and girder bridge carrying IL-89 over the IL River at Spring Valley with a steel plate girder bridge including a 360' navigation span. The main navigation span was included in a 3-span unit, flanked by more modest steel girder span units to either side. A similar solution may



fit conditions at Henry. The bid prices for the Bill of Material on the bridge GPE sheet are in the range of \$27 to \$29 million, resulting in bridge unit costs in the range of 350 to 380 \$/SF.


If IL-18 is replaced by a bridge with similar 43'-2" out-to-out cross section, and at length similar to the existing 1719', the deck area is 74,200. Using the 2015 IL-89 prices, a total bridge cost of \$26 to \$28 million results. Since 2015, the National Highway Construction Cost Index has been rising about 3% per year.


In 2021 dollars, the replacement bridge is estimated to cost \$30 to \$32.5 million.

By (say) 2025, the cost of a replacement steel girder type bridge may be in the range of \$35 to \$37 million.



Attachment A. Location Map







Attachment B. IDOT Master Structure Report

Retrieved from http://apps.dot.illinois.gov/bridgesinfosystem/main.aspx, 4/25/2021

Illinois Department of Transportation Structures Information Management System Structure Summary Report

Date: 04/25/2021

Page: 1

Structure Number:	062-0036	District: 4				
		Inve	ntory Data			
Facility Carried:	ILL 18	Bridge Name: HENRY BRIDGE		Sufficiency Rating:	6.5 Structure Length:	1719.
Feature Crossed:	ILL RIVER, CROMWELL	Location: 1.22 MI E OF ILL	29	HBP Eligible:	Yes AASHTO Bridge Length:	99.9
Bridge Remarks:				Replaced By:	 Length of Long Span: 	364.3
Bridge Status:	1 OPEN - NO RESTRICT	Status Date: 4/20/2020 12:00:00		Replaces:	- Bridge Roadway Width:	22.6
Status Remarks:	LLO signs verified installed as of 4-20-2	AM 0 NRIS insp		Last Update Date:	03/30/2021 Appr Roadway Width:	36.0
Maint County:	062 MARSHALL	Maint Township: 04 HENR	Y	Parallel Structure:	None Deck Width:	23.3
Maint Responsibility:	10 I.D.O.T.	UNKNOWN	•	Multi-Level Structure Nbr:	Sidewalk Width Right:	0.0
Service On/Under:	1 HIGHWAY	6 / HIGHWAY-WATE	RWAY	Skew Direction: N	None Sidewalk Width Left:	0.0
Reporting Agency:	2 I.D.O.T BUREAU OF LOCA			Skew Angle: 0 D	Navigation Control:	1 Yes
Main Span Matl/Type:	3 STEEL	/ 57 PENNSYLVANI	A (PETIT) TRUSS	Structure Flared:	No Navigation Horiz Clear:	338
Nbr Of Main Spans:	1 Nbr Of Approac		. (,	Historical Significance:	No Navigation Vert Clear:	44
Approaches		in opanio.		Border Bridge State:	Culvert Fill Depth:	0.0
Near #1 Matl/Type:	4 STEEL CONTINUOUS	/ 02 STRINGER/MU	TI-REAM/GIRDER	Bdr State SN:	Number Culvert Cells:	0.0
Near #2 Matl/Type:	4 01222 00111110000	/ 02 GTMINGETOWNS	III DE/ (W/OINDEN	Bdr State % Responsibility:	0 Culvert Opening Area:	0.0
Far #1 Matl/Type:	3 STEEL	, / 53 parker trus	S - RIVETED	•	398000 Culvert Cell Height:	0.00
Far #2 Matl/Type:	0.222	/	0 11112125	Substructure Material:	Culvert Cell Width:	0.00
Median Width/Type:	0 Ft. / 0 None	,	Rated By			CTOR (LF)
Guardrail Type L/R: Toll Facility Indicator: Latitude:	0None / 0 0 No Toll 41.10989105 S Longitud		ting: 1.14 Design L		ate: 10/04/2019 FACTOR Crossing 1 Nbr: Crossing 1 Nbr:	ossing Info
Deck Structure Type:	A CIP CON NRMLLY FORM	Deck	Structure Thicknes	ss: 7.5 SD: Y FO:		0.0
Sidewalks Under Struc					RR Vertical Underclear: 0 Ft	0 In
	Key Route On Da			•	oute Under Data	
Key Route Nbr: FEDER			MUNICIPAL S		1340 Station : 0.1600	
Appurtenances Main R		Segment:	Main Route	02545	Segment:	
,	MARSHALL	Linked: Y	062		Linked: Y	
•		atl. Hwy System: Not on NHS	04 HENI		• •	n NHS
Municipality 2545		nventory Direction:		HENRY	Inventory Direction:	
Urban Area: None		urr AADT Yr/Count: 2019 / 220			Curr AADT Yr/Count: 2019	
Functional Class: 4		st Truck Percentage: 4	7 LOCA		Est Truck Percentage:	10
		lumber Of Lanes: 2	South/East	North/West	Number Of Lanes:	2
•		One Or Two Way: 2 Two-V	,	0.0	One Or Two Way: 2	Two-Way
Horizontal: 23		ypass Length: 14	24.0	0.0	Bypass Length:	0
		uture AADT Yr/Cnt: 2032 / 306	+		Future AADT Yr/Cnt: 2032	
Latanal		esignated Truck Rte: CLASS II			Designated Truck Rte: NONE	=
Lateral:		pecial Systems: No			Special Systems: No	
	*** Marked Route On I				Route Under Data ***	
	Designation	Kind Number		Designation	Kind	Number
Route #1: 1 Mainlin		Highway 018		1 Mainline	5 Municipal Streets	
Route #2: 1 Mainlin	ne			1 Mainline		

1 Mainline

Route #3:

1 Mainline

Illinois Department of Transportation Structures Information Management System Structure Summary Report

Date: 04/25/2021

Page: 3

Structure Number: 062-0036 District: 4

Data Related to Inspection Information															
*** Inspe	ction Interval	s ***		*** Maximum Allowable Posting Limits ***								Bridge Posting Level:			
Routine NBIS:	12 MOS	Underwater:	60 MOS	One Tr	uck At A Time:	0	Com	bination	Ту	pe 3S-1:	Tons	L	Legal	Load O	nly
		Special:	N	Single	Unit Vehicles:	LL Tons	Com	bination	Ту	pe 3S-2	Tons				
					Inspection/App	raisal Info	rmation								
Inspection Date:	04/2	20/2020 Inspection	n Temperature:		52Deg. F							** /	Actual Po	sted Li	mits **
Deck:	6	SATISFAC	TORY CONDITI	ONIM - NC	R DETERIORATION	I					Single	Unit Vehic	les:	12	Tons
Superstructure:	3	SERIOUS (CONDITION - SI	GNIFICAN	T SECTION LOSS						Combi	nation Typ	e 3S-1:	41	Tons
Substructure:	4	POOR CON	NDITION - ADVA	NCED DE	TERIORATION						Combi	nation Typ	e 3S-2:	41	Tons
Culvert:	N	NOT APPLI	CABLE								One Tr	uck At A T	ime:	0	
Channel and Protectio	n: 7	GOOD CON	NDITION - SOM	E MINOR F	PROBLEMS	Deck We	earing Surf	f: A	4	BARE DECK NO	OVRLAY	Las	st Paint T	/pe:	1
Structural Evaluation:	3	INTOLERA	BLE - HIGH PRI	ORITY FO	R CORRECTION	Deck Me	mbrane:	F	=	NONE		ALUM E	POXY MA	ASTIC	
Deck Geometry:	2	INTOLERA	BLE - HIGH PRI	ORITY FO	R REPLACEMENT	Deck Pr	otection:	A	4	EPOXY COATE	D REINF				
Underclearance-Vert/L	at.: 2	INTOLERA	BLE - HIGH PRI	ORITY FO	R REPLACEMENT	Total De	ck Thick:	7	7.5						
Waterway Adequacy:	8	EQUAL TO	PRESENT DES	IRABLE C	RITERIA	Last Pai	nt Date:	0	06/1	988					
Approach Roadway Al	ign: 7	BETTER TH	HAN PRESENT	MINIMUM	CRITERIA										
Bridge Railing Apprais	al: 3	Meets Stan	dards												
Approach Guardrail:	332	Acceptable	Accepta	able	Not Acceptable										
Pier Navig Protection:	1	NAVIGATIO	ON PROTECTIO	N NOT RE	QUIRED										
				Unde	rwater Inspection	on/Appraisa	al Inform	ation							
Inspection Date:	04/20/2020														
Temperature:	52	Inspection I	Method:	PS	Probe Appra	isal Rating:		onar OOD CO	ND	ITION					

	Scour Critical Information							Miscellaneous			
Rating:	5	CALCULAT	TED SCOUR ACCEP	TABLE	Eva	luation Method:	Α	Computer Calculation			
Analysis Date: 01/05/1995								Microfilm Data Recorded:	Yes		
			Construction	Informatio	n						
Year:	1934	Original		1988	Reconstructed						
Route:	SBI-89	OC .	Sta: 12+05	FAS2369		Sta: 13+91.88					

Fed Aid Pr#: 0000000000000 BHS-2369(101)

104-B

Section Nbr:

Contract Nbr:

Built By: 1 I.D.O.T. 0 UNKNOWN

104B-D

42926




Attachment C. Bridge Inspection Report

4/20/2020 Detailed Inspection Report (Eric Rent, IDOT)

HENRY BRIDGE IL 18 over the Illinois River

SN 062-0036



Inspection Report

April 20, 2020

Prepared by
Illinois Department of Transportation
(Eric Rent)
Bridge Inspection Technician

TABLE OF CONTENTS

- 1) NBIS Bridge Inspection Report
- 2) Fracture Critical Inspection Report
- Underwater Inspection Report with Elevation Sheets
- 4) Element Level Inspection Report
- 5) Framing Plan, Table of Deficiencies and Photos
- 6) Table of Joint Openings



Routine Inspection Report

SN: 062-0036	District:		Spans: 1		Spans:13	Skew: 0) AD	T: 2600	Truck Pct	
ADT Un: 275	Maint. Co	: N	IARSHALL	Tw	-			Status		STRICT
Facility Carried: IL 18					Feature (IL RIVE			
Location: 1.22 MI. EAST			Municipality: HE	ENRY	34 1		Sub Section:			888
Bridge Name: HENRY I		h	Emantuma Cuitinale	24	Underwa				NIA (PETIT) TRU	
Insp. Intervals Routine: 90 – Inspection Date:	24 04 / 20 / 2		Fracture Critical:	24		emp. (°F):	Special: 52	NA	Element Level: 90B1 – In Depth:	24
Is Delinquent:	Reason:	2020			90C - I	emp. (1 ⁻).	32		90 b 1 – III Deptii.	
90A – Agency Program M		STE	VE NEGANGAR	PD	90A3 – (Consultant	Program M	anager:		
	SHANE SU						ERIC RE			
90A1 – Team Leader: SHANE SUMMER 90B– Inspection Remarks: DECK -2% SPALL/DELAM/MAP CRACK TRANV. CRKS. 5' TO 10' APART, MAJORITY @ 10'. <1% SPALL/DELAM SUPER - S.L. UP TO 49% WEB BRG. LOSS, S.L. UP TO 39% ON TRUSS MEMBERS S.L. UP TO 24% BOT. FLG. LOSS ON FLOORBEAMS SUB - LARGE SPALLS W/ EXP. REBAR. LOSS OF BRG. UP TO 25% ON BENT 5, & 21% ON P 7 TRUSS BRG. BENTS B5 & B6 ARE LEANING NORTH										
				Res	ources					
Time to Inspect (H:M):	30:00	30:0	0 Traffic Cont	rol:	Y Y Bo	oat: Y	Y Wade	ers:	Snooper:	2 2
Ladder: Manli			Bucket Truck:		Other:				1 1	_
			Inspe	ector	's Appra	nisals				
	Prev	New	•				Comments			
58 – Deck Condition:	<u>6</u>	6	SEE 90B							
59 – Superstructure Con	d: <u>3</u>	3	SEE 90B							
•										
60 – Substructure Cond:	4	4	SEE 90B							
62 – Culvert Condition:	=	-								
61 – Channel Condition:	: <u>7</u>	7								
71 – Waterway Adequad	ey: <u>8</u>	8								
72 – Approach Rdwy Al	lign: <u>7</u>	7								
111 P. W. D. C.	1	1								
111 – Pier Navig Protecti	on: <u>1</u>	1								
			90B – I	nspe	ction Re	emarks:				
DECK -2% SPALL/DELA	AM/MAP C	RAC	CK TRANV. CR	KS. 5' 7	TO 10' APA	RT, MAJ	ORITY @ 1	0'. <1% S	PALL/DELAM	
SUPER - S.L. UP TO 49%	6 WEB BR	G. LO	OSS, S.L. UP TO	39% (ON TRUSS	MEMBEI	RS			
S.L. UP TO 24% BOT. FI	LG. LOSS (ON F	LOORBEAMS							
SUB - LARGE SPALLS W/ EXP. REBAR. LOSS OF BRG. UP TO 25% ON BENT 5, & 21% ON P 7 TRUSS BRG.										
BENTS B5 & B6 ARE L	BENTS B5 & B6 ARE LEANING NORTH									

Routine Inspection Report

Structure Number: 062-0036

	Pi	Addition New New	onal In	spec	tion Da	ta						
36A – Bridge Railing Ad	equacy:	3 Rail	Types:	New				Prev No	-w		Prev	New
Approach Guardra	ail Adequacy: 36E	3 – Transition		3	36C – Gu	ıardrai	1:			36D – Ends		2
108A – Wearing Surface		<u>A</u> A 108B	– Type of	Mem	hrane:	Prev F	New F	108C -	- Dec	k Protection		Prev New
108D – Total Deck Thick			1,700 01	1,10111			-	1000		K 1 Totoction		<u> </u>
		Prev Ne										
59A – Paint Date (Mo/Yr	r): <u>06</u>	<u>5 / 88</u> 06 / 8	8									
59B – Paint Type:	<u> </u>	¹			Color: F	ascia -	– <u>GF</u>	REY; I	nter.	– <u>GRN</u> ; Ra	iling –	
59C – Utilities Attached:		_ 9 9										
						Prev		New	٦			
	70A2 – Single U					<u>28</u>		Tons	+			
Weight Limit Posting:	70B2 – Combina					<u>35</u>		Tons	+			
	70C2 – Combina 70D2 – One Truc		-2 (5 or m	nore ax	(les):	<u>35</u>	41	Tons				
	70D2 – One Truc	ck at a Time:										
Joint Openings (In.)												
	90B	3 – Inspec	tion Re	mar	ks Cont	tinue	d:					
Inspection Team Leader:	1	/		Sign	ature					04 / 2	Date 22 / 20	20
Consultant Program Mar	/~ /	hone	Lun	~~	~					04 / 2		20
Agency Program Manage	_	ve Nega	nann	L							 1/ 2	020
3		- 10 ega	gwa									



Fracture Critical Inspection Report

SN: 062-0036 District: 4 Spans: 1 Appr. Spans: 13 Skew: 0 ADT: 2250 Truck Pct: 6
ADT Un: 275 Maint. Co: MARSHALL Twsp: HENRY Status: OPEN NO RESTRICT
Facility Carried: IL 18 Feature Crossed: IL RIVER, CROMWELL Location: 1.22 MI. EAST OF IL 29 Municipality: HENRY Team/Sub Section: 344/181 Insp/Rte: 888
Bridge Name: HENRY BRIDGE Material & Type: STL./PENNSYLVANIA (PETIT) TRUSS
Insp. Intervals Routine: 24 Fracture Critical: 24 Underwater: 60 Special: NA Element Level: 24
93A- Inspection Date: 04 / 20 / 2020 93A4- Temp. (°F): 52
Is Delinquent: Reason:
90A – Agency Program Manager: STEVE NEGANGARD 90A3 – Consultant Program Manager:
93A3 – Team Leader: SHANE SUMMER 93A5 – Inspector: ERIC RENT
Resources
Time to Inspect (H:M): 30:00 30:00 Traffic Control: Y Y Boat: Y Y Waders: Snooper: 2 2 Ladder: Manlift: 1 1 Bucket Truck: Other:
Ladder:
Inspector's Appraisals
92A1-Type: X2 If "X4-Other" Description: SPANS 3 - 8
93A1-Rating: Prev. <u>5</u> New <u>5</u> FC Method: Prev. <u>V</u> New: MP _ DP _ UT _ V _
93A2-Remarks: S.L. UP TO 18% BOT. FLG. LOSS & 13% WEB LOSS ON FLOORBEAMS.
BIBLET 10 10 /0 DOTATED BOSS & 10 /0 (VBB BOSS OTATED OTABLE MAIS)
02A1 Type: D5 ISSVA Od-22 D-22 intime CDANC 2 0
92A1-Type: B5 If "X4-Other" Description: SPANS 3 - 8 93A1-Rating: Prev. 5 New 5 FC Method: Prev. V New: MP DP UT V
93A2-Remarks: MBRS: L0 - L4, L1 - U1, L2 - U2, L3 - U3, L4 - U4, U1 - L2, U2 - L3, U3 - L4, L3 - U4. (SPANS 3, 4, 6,
7 & 8) (SPAN 5) L0 - L5, M1 - L1, U2 - L2, M3 - L3, M5 - L5, U6 - L6, M7 - L7, U2 - M3, M3 - L4, U4 - M5, M5 - L6, U6 - M7.
S.L. UP TO 18% ON TRUSS MEMBERS.
92A1-Type: If "X4-Other" Description:
93A1-Rating: Prev. New FC Method: Prev. New: MP DP UT V
93A2-Remarks:
92A1-Type: If "X4-Other" Description:
93A1-Rating: Prev. New FC Method: Prev. New: MP DP UT V
93A2-Remarks:

92A1-Type: If "X4-Ot	her" Description:							
93A1-Rating: Prev. New	FC Method: Prev	v N	lew: MP DP	UT V				
93A2-Remarks:								
	her" Description:		. Mr					
93A1-Rating: Prev. New 93A2-Remarks:	FC Method: Prev	/ N	lew: MP □ DP					
93A2-Remarks:								
92A1-Type: If "X4-Ot	her" Description:							
93A1-Rating: Prev. New	FC Method: Prev	<i>i</i> N	lew: MP DP	UT V				
93A2-Remarks:								
	her" Description:							
93A1-Rating: Prev. New	FC Method: Prev	V N	lew: MP □ DP					
93A2-Remarks:								
92A1-Type: If "X4-Ot	her" Description:							
93A1-Rating: Prev. New	FC Method: Prev	ı N	lew: MP □ DP	UT V				
93A2-Remarks:	Te Mediod. Tree		.cw. 1411 B1					
		Signature		Date				
Inspection Team Leader:	Shan. In	1.00		04 / 22 / 2020				
Consultant Program Manager:	7 7 55.			1 1				
Agency Program Manager:	Steve Negang	and.		8 /11/2020				
Agency 110gram Wanager:	Jane 10 egung	·ww		0 / 11/2020				
Two Girder Al Supposion Link & Din Pl Evolution		Cable Stayed & Suspension	Box Beams					
A2- Suspension Single Pin B2- Simple	& Pin Tension Members C1- Suspension Bridge- Cables F1- Single Welded Box Span Welded Truss C2- Cable Stayed- Cables F2- Single Riveted/Bolted Box							
A3- Tension Flanges Riveted/ Tension	Members	Tied Arches D1- Welded Box Ties	F3- Double	Box Beam- Welded,				
Bolted Plate Girders B3- Hanger A4- Bearing Seat of Suspended Trusses	Link & Pin of Suspended	D1- Welded Box Ties D2- Riveted/Bolted Box Ties	Riveted Other Type	l or Bolted <u>es</u>				
	Element Tension Members	D3- Stiffened Girders	X1- Bascule					

- A5- Tension Flange of Rolled
- Beam A6- Tension Flange of Welded Plate Girders
- A7- Tension Flanges of Lattice Truss Web Girders
- B5- Simple Span Riveted/Bolted Tension Members
- B6- Continuous Truss System- Welded, Riveted or Bolted Tension Members

Framed Steel Substructure


- E1- Welded or Rolled Pier Cap E2- Riveted or Bolted Pier Cap
- E3- Welded or Rolled Pier Column E4- Riveted or Bolted Pier Column
- X2- Floorbeams supporting other steel members or spacing > 15 ft.
- X3- Cross Frames or Transfer Beams
- X4- Other



Underwater Inspection Report

SN: 062-0036 Distric	ct: 4 Spans: 1	Appr. Spans:13 Ske	ew: 0 ADT: 2600	Truck Pct: 5
ADT Un: 275 Maint. 0	Co: MARSHALL	Twsp: HENRY		: OPEN NO RESTRICT
Facility Carried: IL 18			ed: IL RIVER, CROM	
Location: 1.22 MI. EAST OF IL 2	9 Municipality: H		m/Sub Section: 344/18	
Bridge Name: HENRY BRIDGE	<u> </u>		e: STL./PENNSYLVAN	
Insp. Intervals Routine: 24	Fracture Critica			Element Level: 24
93B– Inspection Date: 04 / 20		93B6- Temp. (°F): 52	
Is Delinquent: Reason		2010 0		
90A – Agency Program Manager:			Iltant Program Manager	:
93B2 - Underwater Inspection R	SUMMER emarks:	93B7 – Inspec	ctor: ERIC RENT	
Previous				
		Resources		
Time to Inspect (H:M): 2::00 Ladder: Manlift:	2:00 Traffic Con Bucket Truck:	trol: Boat: Other:	Y Waders:	Snooper:
	Insp	ector's Appraisals		
02B9 Suba	structure Units Inspecte	al.	93B1- Rating	
	structure offits inspected	u	Prev New	
PIERS 2, 3, 4	New		<u>7</u> 7	
93B4 – Method: <u>S P S P</u>	If "O-Other"	Describe:		
	93B2 – Under	rwater Inspection F	Remarks:	
MINOR SCOUR 3'- 4' AROUND F	PIERS. NOTED IN 2	017.		
		Signature		Date
Inspection Team Leader:	Shone &	lumma		04 / 22 / 2020
Consultant Program Manager:				/ /
Agency Program Manager	Steve Nega	ngard		8 / 11/2020

PIER 2



DETAIL A

UNDERWATER INVESTIGATION

SHEET 1 OF 3

STRUCTURE NUMBER: 062-0036 WATER ELEVATION: 441.5'

INSPECTION DATE: 4/20/2020

INSPECTED BY: SMS, JDD DETAIL / DIM. / ELEV.: A/20.1'/461.6'

	50'	25'	EDGE	CENTER LINE	EDGE	25'	50'
50' (+/-)			441	440	440	437	433
25' (+/-)		BANK	441	440	440	437	433
EDGE				440 PIER: 2	440	437	434
C.L.		BANK		FLOW DIR.: TOP PILE CAP ELEVATION: 414.6 BOT. PILE CAP ELEVATION: 412.1 BOT. SEALCOAT ELEVATION: 409.1 DESIGN S.B. ELEVATION: 436.6	441	437	434
EDGE				441	441	437	434
25' (+/-)		BANK	441	441	441	438	434
50' (+/-)			441	441	441	438	435

UNDERWATER INVESTIGATION SHEET 2 OF 3

STRUCTURE NUMBER: 062-0036 WATER ELEVATION: 441.5'

INSPECTION DATE: 4/20/2020

INSPECTED BY: SMS, JDD **DETAIL / DIM. / ELEV.:** A/20.1'/461.6'

	50'	25'	EDGE	CENTER LINE	EDGE	25'	50'
50' (+/-)	427	426	426	427	427	427	425
25' (+/-)	427	428	427	422	422	426	425
EDGE	424	423	423	419	419	426	426
C.L.	422	422	420	PIER: 3 FLOW DIR.: TOP PILE CAP ELEVATION: 410.6 BOT. PILE CAP ELEVATION: 408.2 BOT. SEALCOAT ELEVATION: 405.2 DESIGN S.B. ELEVATION: 426.2	420	424	426
EDGE	422	423	422	421	421	424	426
25' (+/-)	423	423	420	420	422	424	425
50' (+/-)	424	424	423	423	424	425	424

UNDERWATER INVESTIGATION SHEET 3 OF 3

STRUCTURE NUMBER: 062-0036 WATER ELEVATION: 441.5'

INSPECTION DATE: 4/20/2020

INSPECTED BY: SMS, JDD **DETAIL / DIM. / ELEV.:** A/20.1'/461.6'

	50'	25'	EDGE	CENTER LINE	EDGE	25'	50'
50' (+/-)	429	430	431	431	433	433	437
25' (+/-)	430	431	431	431	432	433	436
EDGE	430	431	431	430	430	431	436
C.L.	430	431	427	PIER: 4 FLOW DIR.: TOP PILE CAP ELEVATION: 410.7 BOT. PILE CAP ELEVATION: 408.2 BOT. SEALCOAT ELEVATION: 405.2 DESIGN S.B. ELEVATION: 432.4	430	431	435
EDGE	430	430	430	430	430	431	434
25' (+/-)	430	431	432	432	432	434	435
50' (+/-)	430	432	431	431	433	433	436



Element Level Inspection Report

SN: 062-0036	District:	4 Spans: 1	Appr.	Spans: 13	Skew: (O = A	ADT: 2600	,	Truck Pct: 5
ADT Un: 275 Maint. Co: MARSHALL Tw				HENRY			Status: OPEN	NO RI	ESTRICT
Facility Carried: IL 18		Feature Crossed	: IL RIV	VER, C	ROMWELL				
Location: 1.22 MI. EAST OF	F IL 29	Municipa	ality: H	ENRY	Team/S	Sub Sec	tion: 344//18	1	Insp/Rte: 888
Bridge Name: HENRY BRII	OGE			Material & Type: STL./PENNSYLVANIA (PETIT) TRUS					
Insp. Intervals Routine: 24		Fracture Critical:	24	Underwater: 6	0 5	Special:	: NA	Elem	ent Level: 24
93C– Inspection Date: 04	0		93C6– Temp. (°F): 52						
Is Delinquent: Rea	ason:								
90E-Agency Program Manag	ger: STE	VE NEGANGAR	D	90E3-Consultant Program Manager:					
90E1– Team Leader: SHA	ANE SUMN	MER		90E2- Inspecto	or: ER	IC RE	NT		
Resources									
Time to Inspect (H:M): $30:0$ 30:0 Traffic Control: Y Y Boat: Y Y Waders: Y Snooper: Y 2									
Ladder: _ Manlift:	: <u>1</u> 1	Bucket Truck: _		Other:					

Inspector's Appraisals


Element	Element Description	Env	Quantity	Unit	CS1	CS2	CS3	CS4
12	Reinforced Conc. Deck	2	39995	LF	37599	2396	0	0
	Remarks							
8102	Steel Beam/Gir./Stringer End	2	20	EA	4	4	0	12
	Remarks							
107	Steel Open Girder/ Beam	2	1370	LF	1131	229	0	10
	Remarks	•		•		•		•
113	Steel Stringer	2	5488	LF	5303	185	0	0
	Remarks	•		•		•		•
120	Steel Truss	2	2744	LF	0	2739	0	5
	Remarks	•						
152	Steel FloorBeam	2	1440	LF	792	613	0	35
	Remarks			II.	-			
162	Steel Gusset Plate	2	508	EA	50	458	0	0
	Remarks						<u> </u>	
205	Reinforced Concrete Column	1	12	EA	0	0	0	12
	Remarks						1 -	. –
210	Reinforced Concrete Pier wall	1	271	LF	201	30	30	10
-	Remarks					1 00	1 00	
215	Reinforced Conc. Abutment	1	74	LF	59	15	0	0
	Remarks				, 00	1.0	<u> </u>	, ,
227	Reinforced Conc. Pile Extension	1	30	EA	6	6	6	12
	Remarks							<u> – </u>
234	Reinforced Conc. Pier or Abutment Cap	1	286	LF	207	55	15	9
_	Remarks					1 00	1 .0	<u> </u>
300	Strip Seal Exp. Jnt.	2	115	LF	8	68	6	33
	Remarks				1 -	, 00		
302	Compression Jt. Seal	2	50	LF	2	48	0	0
	Remarks				ı –		<u>, </u>	<u>, </u>
305	Assembly Jt. W/O Seal	2	23	LF	0	23	0	0
	Remarks				, •	1 20	<u>, </u>	<u>, </u>
310	Elastomeric Bearing	2	42	EA	8	30	4	0
	Remarks				. •	, 55		,
311	Movable Brg.	2	8	EA	0	4	4	0
	Remarks			, .	. ~			, ,
313	Fixed Bearing	2	18	EA	10	8	0	0
	Remarks			. –				, ,
330	Metal Bridge Railing	2	3435	LF	3435	0	0	0
220	Remarks		, 0.00		0.00		<u>, </u>	


Element Level Inspection Report


Structure Number:

Element	Element Description	Env	Quantity	Unit	CS1	CS2	CS3	CS4
515	Steel Protective Coating	2	133868	SF	86393	0	0	47475
	Remarks		1		•	_		_
	_							
	Remarks		1		<u> </u>		1	1
	Remarks				<u> </u>			
	Remarks							
	Remarks	<u> </u>		1				1
					0			
	Remarks				•	•	•	•
					0			
	Remarks		1		•	_	1	_
					0			
	Remarks		T	1	T _		1	1
	2				0			
	Remarks		I					1
	Remarks				0			1
	Remarks				0			
	Remarks				1 0			1
	Remarks				0			
	Remarks		1	1				
					0			
	Remarks				•	•	•	•
					0			
	Remarks					_		
					0			
	Remarks		T	1			1	1
	P 1				0			
	Remarks		I					1
	Remarks				0			
	Remarks				0			
	Remarks				1 0			
	Remarks				0			
	Remarks	l .		1				<u> </u>
	1				0			
	Remarks	•						
					0			
	Remarks		T		T	T	1	_
					0			
	Remarks		T			1	1	1
	D 1				0	1		1
	Remarks					1		1
	Domonto				0	1		1
	Remarks				0	1	<u> </u>	T
	Pamarks			1	U			1
	Remarks	l .	<u> </u>		ı U			

	Signature	Date
Inspection Team Leader:	Show Sum	04 / 22 / 2020
Consultant Program Manager:	-	/ /
Agency Program Manager:	Steve Negangard	8 /11 / 2020







1 = Typical Paint

= ITEM # IN DEF. TABLE


= DIRECTION OF PHOTO TAKEN

2) = Typical Deck

53 = TREES

(72) = RAIL

Henry 062-0036 PAGE 1



MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 **YEAR: 2020**

% S.L. SHOWN IS ESTIMATED

	* See report from year indicated for photo of c							
ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН
1	ALL	PAINT	GENERAL	1, 2, 3, 4, 5	89% CS1, 11% CS2, <1% CS3, <1% CS4 SURFACE RUST FORMING	ZONE PAINTING (SOON)		
2	ALL	DECK	GENERAL	6, 7, 8, 9	94% CS1, 6% CS2 (TRANV. CRK. 5' TO 10' APART)	MONITOR	01	
53	7,8	TREES	E & W SIDES	10, 11	TREES OBSTRUCTING INSPECTION ACCESS	TRIM	15	
72	4,5,8	RAIL	GENERAL	SEE TABLE	BOLTS MISSING IN RAIL (SEE TABLE 10)	MONITOR	17	
3	2, 3	P 1	E & W FACE OF CRASH WALL	12, 13	100 SQ. FT. DELAM./ SPALL	MONITOR	01	
96	3	L0E – U1E	@ TOP OF RAIL	14	6" X 1" OFFSET	MONITOR	19	X
4	3	L1E - L2E	12' FROM L1E	15	2 - PLUG WELDS	MONITOR	05	
97	3	CONDUIT	MIDSPAN L1E-L2E	16	BROKEN/EXPOSED WIRES	REPAIR	19	
5	3	U1W - L2W	8' ABOVE DECK	17	1 - PLUG WELD	MONITOR	03	
54	3	U2E – U2W	@ C.L. BOTH SIDES	18	9" X 1" OFFSET	MONITOR	15	X
98	3	SWAY BRACE	P.P. 2 LOWER HORZ. ABOVE BOTH LANES	19	2 – 9' X 1" OFFSETS	MONITOR	19	
73	3	L2W-L3W	@ L3W	20	3/4" MISDRILLED HOLE INSIDE BOTTOM ANGLE (NO HOLE IN COVER PLATE)	MONITOR	17	
99	3	L3E – U4E	@ L3E	21	16% S.L., (SEE DETAIL 3)	MONITOR	19	
6	3	GUSSET PL.	@ L3W O.S.	23	1 – PLUG WELD (BOT.)	MONITOR	09	
100	3	SWAY BRACE	P.P. 4 LOWER HORZ. ABOVE E.B. LANE	22	7" X 1 ½" OFFSET	MONITOR	19	
101	3	SWAY BRACE	P.P. 6 LOWER HORZ. ABOVE E.B. LANE	24	6" X ¾" OFFSET	MONITOR	19	
7	3	L6W U6W	4' ABOVE DECK	*2015	3" X ½" OFFSET	REPAIRED	05	
8	3	L6W – U7W	LEVEL WITH DECK	25	2 – PLUG WELDS	MONITOR PER RON RODKEY		
9	3	L6W - U7W	3' ABOVE DECK	26	3" X ¼" OFFSET	MONITOR		
147	3	L6W-L7W	@ L7W	27	3/4" MISDRILLED HOLE INSIDE BOTTOM ANGLE (NO HOLE IN COVER PLATE)	MONITOR	20	X

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 YEAR: 2020

% S.L. SHOWN IS ESTIMATED

* See report from year indicated for photo of deficit								
ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН
10			THROUGHOUT 28, 29		23% S.L. IN BOT. FLG., 14% S.L. TOP FLG., 2% S.L. IN WEB, 2" HOLE IN BOT OF STIFF. @ STR. 2 & 3, 5" HOLE IN BOT. OF STIFF., @ STR. 4, S. FACE OF BM. & 3" HOLE IN BOT. OF STIFF. @ STR. 1, S. FACE OF BM. (SEE DETAIL 1)	REPAIR 17% S.L. BOT. FLG., IRF= 1.26	13	X
11	3, 4	JOINT	@ P 2, EAST & WEST ENDS	30	9' OF JOINT FAILED/LEAKING, 8' E. END, 1' W. END	REPAIR IMMEDEIATELY	13	
12	3,4	P 2	WALL & COL.	31, 32	500 SQ. FT. DELAM./SPALL ON WALL 200 SQ. FT. DELAM./SPALL ON COL. (6% S.L. COLUMN, DETAIL 14)	MONITOR	01	
148	4	FB. 0	@ STR. 1	28	3" HOLE IN BOT. OF STIFF.	MONITOR	20	X
102	4	L0E – U1E	@ L0E	33	10% S.L., 2'' HOLE IN STAY PL.	MONITOR	19	
13	4	L1E - L2E	@ L1E BOTH LEGS OF L.C.	34	2 - PLUG WELDS	MONITOR	05	
14	4	L1W - L2W	@ L1W BOTH LEGS OF L.C.	35	2 - PLUG WELDS	MONITOR	05	
55	4	U2E – U3W	@ MIDSPAN, PAN 3	36	14% S.L. 7/8" MISDRILLED HOLE	MONITOR	15	
56	4	L3W – U3W	@ L3W	37	6% S.L., 3/4" MISSDRILLED HOLE IN STAY PL.	MONITOR	15	
15	4	L3W – L4W	@ L3W	38	2 - PLUG WELDS	MONITOR	01	
149	4	CONDUIT	2' N OF L4E	39	BROKEN/ EXPOSED WIRES	REPAIR	20	X
16	4	L5E L6E	@ L5E	*2017	PART. CRK. T.W.	REPAIR NOT A CRACK	01	
57	4	U5E – U6W	@ MIDSPAN, PAN 6	40	14% S.L. 1" MISSDRILLED HOLE	MONITOR	15	
17	4	L6W - U7W	2' ABOVE DECK	41	5" X 1/2" OFFSET WITH 1" X 1/16"D GOUGE	MONITOR		
18	4	L6W - L7W	@ L7W BOTH LEGS OF L.C.	42	2 - PLUG WELDS	MONITOR	05	
74	4	L7E-U7E	4' ABOVE DECK, INSIDE ANGLE	43	7% S.L. 2-7/8" ABANDONED HOLES	REPAIR	17	

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 YEAR: 2020

% S.L. SHOWN IS ESTIMATED

* See report from year indicated for photo of defic								ency
ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН
103	4	L7W – L8W	@ L8W	44	9% S.L., (SEE DETAIL 17) 30% S.L., 2-4" HOLES IN STAY PL.	MONITOR	19	X
58	4	L7W – L8E	@ L8E	45	50% S.L. 8" X 4"" HOLE IN BOT. CONN. PL.	MONITOR	15	
19	4	FB. 8	THROUGHOUT	46, 47	17% S.L. IN WEB, 25% S.L. IN BOT. FLG., 9% S.L. TOP FLG., 4" HOLE IN 1 ST STIFF. FROM E & W TRUSS S. FACE SEE DETAIL 2	REPAIR 18% S.L. BOT. FLG., IRF= 1.22	13	X
20	4, 5	CONDUIT	P 3, BTWN. FB. 8 & FB. 0, WEST END	48	BROKEN SUPPORT FOR CONDUIT, EXPOSED WIRES	REPAIR	13	X
21	4, 5	Р3	WALL, CAP, COL. & WEST BRG. OF SP. 4	49, 50	100 SQ. FT. DELAM./SPALL IN WALL WITH 1/8" CRK. FULL PERIMETER 50 SQ. FT. DELAM./SPALL ON CAP, & 2% BEARING LOSS, SP 4 WEST BRG. 60 SQ. FT. DELAM/SPALL. COL. (3% S.L. COLUMN, SEE DETAIL 15)	MONITOR	03	
59	4, 5	JOINT	@ P 3, WEST END	51	7' FAILED, LEAKING	REPAIR IMMEDIATELY	15	
104	5	FB 0	THROUGHOUT	52, 53	9% S.L., BOT. FLG., 7% S.L., TOP FLG., 4% S.L. WEB (SEE DETAIL 18) 4" HOLES IN 1 ST STIFF. FROM E & W, N. FACE	MONITOR	19	
75	5	L1E-U1E	1' ABOVE DECK	54	3% S.L., 1-7/8" MISDRILLED HOLE (THROUGH 1 ANGLE NOT BOTH)	MONITOR	17	
105	5	U1E - U1W	ABOVE EB LANE	55	18" X ½ " & 6" X ½ " OFFSETS	MONITOR	19	
22	5	L1E – L2E	4' FROM L1E	56	10% S.L., 1" HOLE IN TOP BAT. PL.	MONITOR	13	
76	5	L2E-U2E	@ L2E	57	7% S.L., INSIDE LEGS HAVE .4433 AVG REMAIN. 5"X 3"X 9/16" ANGLES	MONITIR	17	
23	5	SWAY BRACE	P.P. 4 LOWER HORIZ. E SIDE 1' 3" FROM L4E U4E	* 2015	12" X 1 ½" OFFSET	REPAIRED	01	
77	5	L3E-L5E	@ L4E, T. INSIDE ANGLE	58	5 PLUG WELDS	MONITOR	17	X

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 YEAR: 2020

% S.L. SHOWN IS ESTIMATED

	* See report from year indicated for photo of							l
ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН
24	5	L3W – L5W	@ L4W – TOP INSIDE ANGLE, EA. SIDE OF L4W	59, 60	PLUG WELDS (5 ON EA. SIDE), 20% S.L., 2-2" HOLES IN T. STAY PL.	MONITOR	09	X
60	5	U4E – U5W	@ MIDSPAN, PAN 5	61	12" X 1/2" OFFSET IN BOT. ANGLE	MONITOR	15	
25	5	L4E – L5E	@ L5E	62	4" X 3/4" OFFSET ON TOP STAY PLATE	MONITOR	09	
26	5	NAV. LIGHT	E & W. SIDE @ P.P. 7	63	NAV. LIGHT LENS IS BROKEN, & SUPPORT IS BENT	REPAIR	13	
150	5	L7W-L8W	3 RD BAT. PL. FROM L7W	64	40% S.L., 2" HOLE IN T. BAT. PL	MONITOR	20	X
61	5	U9E – U9W	@ C.L.	65	10" X 1/2" OFFSET	MONITOR	15	
151	5	RAIL POST SUPPORT	1ST S. OF L9W	66	50% S.L., 5" HOLE IN WEB	REPAIR	20	X
27	5	RAIL POST SUPPORT	1 ST S. OF L10E	67	60% S.L., 6" HOLE IN WEB	REPAIR	13	
28	5	L12W – L13W	@ L12W	68	10" X 1/4" OFFSETS IN BOT. IS. & OS. ANGLES	MONITOR	11	
78	5	U13W-L14W	@ 10' ABOVE DECK	69	18" X 3 ½" OFFSET	MONITOR	17	
29	5, 6	JOINT	<u>@ P 4</u>	*2017	DEBRIS IN FINGER JOINT	CLEANED	07	
30	5, 6	P. 4	CAP, COLUMN, & WALL	70, 71	20 SQ. FT. SPALL/DELAM ON CAP, 100 SQ. FT. SPALL / DELAM ON COL. 60 SQ. FT. SPALL / DELAM ON WALL (4% S.L. COLUMN, DETAIL 16)	MONITOR	05	
79	6	L0E-L1E	THROUHGOUT	72	4% S.L., (SEE DETAIL 12) 50% S.L. 10"L X 3" HOLE IN BOTTOM STAY PL	MONITOR	17	
106	6	L1W – L2W	1' FROM L1W	73	6% S.L., 2-7/8" MISDRILLED HOLES IN INSIDE VERTICAL LEGS OF ANGLE 2 PER SECTION, NO HOLE IN COVER PL.	MONITOR	19	
80	6	U1E-L2E	7' ABOVE DECK	74	7" X ¼" OFFSET	MONITOR	17	
107	6	SWAY BRACE	P.P. 2 LOWER HORZ. E.B. LANE	75	8" X ½ " OFFSET	MONITOR	19	
108	6	U2E – L3E	@ L3E	76	13% S.L., (SEE DETAIL 3)	REPAIR		
109	6	L3E – U4E	@ L3E	76	6% S.L., (SEE DETAIL 3)	MONITOR		
31	6	6 SWAY BRACE P.P. 3 ON E SIDE LOWER HORIZ. 4' FROM E. TRUSS		* 2015	12" X 1" OFFSET	REPAIRED	01	

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 YEAR: 2020

% S.L. SHOWN IS ESTIMATED

	I	l	* See report from year indicated for photo of defi						
ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН	
32	6	SWAY BRACE	P.P. 4 ON E SIDE LOWER HORIZ.4 1/2' FROM E. TRUSS	*2 015	8" X 1 ½" OFFSET	REPAIRED	01		
81	6	U3E-L4E	@ L4E	77	9% S.L. SEE DETAIL 3	MONITOR	17		
62	6	L4W – U4W	4' ABOVE DECK, INSIDE CHANNEL	?	4" X 3/4" OFFSET	MONITOR	15		
82	6	L4E-U5E	@ L4E	78	8% S.L. SEE DETAIL 3	MONITOR	17		
110	6	U4E – L5E	@ L5E	79	10%S.L., (SEE DETAIL 3)	MONITOR	19		
33	6	SWAY BRACE	P.P. 5 ON LOWER HORIZ. 3' E & 3' W. OF C.L.	* 2015	4' 6" X 3/8" OFFSET, 12"X1/2" OFFSET	REPAIRED	09		
34	6	L5E - L6E	@ L6E ON BOT. OUTSIDE ANGLE OF L.C.	80	1 PLUG WELD	MONITOR	05		
35	6	L7W - U7W	2' ABOVE DECK	81	8 – PLUG WELDS @ 2'	MONITOR	99		
36	6	L7W – L8W	@ L7W	82	3 PLUG WELDS BOTH SIDES OF L.C.	MONITOR	09		
111	6	W. BRG.	@ P5	83	6% BRG. LOSS, 2" X 14" CORNER, PL. 33" X 15"	MONITOR	19		
112	6	FB8	THROUGHOUT	84	10% S.L. IN WEB, 8% S.L. IN TOP FLG., 6% S.L. IN BOT. FLG., (SEE DETAIL 19) 3" HOLES IN 1 ST STIFF. FROM E & W, N. FACE	MONITOR	19		
37	6, 7	P 5	CAP & COLUMNS	85, 86	70 SQ. FT. DELAM/SPALL ON COLS., 60 SQ. FT. DELAM/SPALL ON CAP 4 EXPOSED BARS 2 BROKEN @ W. CAP SPALLING AROUND BRG., NO BRG. LOSS	MONITOR	05		
63	6, 7	JOINT	@ P 5, EAST & WEST END	87	7' FAILED, 2' EACH END, 3' @ CTR.	REPAIR	15		

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 YEAR: 2020

% S.L. SHOWN IS ESTIMATED

* See report from year indicated for photo of deficiency								
ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН
64	7	FB. 0	THROUGHOUT	88	16% S.L. IN WEB @ E. END, 15% S.L. IN TOP FLG. & 13% S.L. IN BOT. FLG. NEAR C.L., (SEE DETAIL 7) STIFF. @ S1 3" HOLE BOT. STIFF. @ S4 1" HOLE BOT.	REPAIR, RATE 13% S.L. WEB, IRF WEB=2.77	15	X
152	7	L0E-U1E	@ L0E	89	20% S.L., 10" X 2" HOLE IN BOT. STAY PL., 2" HOLE IN 11 TH LAC. BAR FROM LOE	MONITOR	20	X
83	7	L0W-L1E	@ LOW, CONN. PL	90	60% S.L., 8" X 8" HOLE IN CONN. PL	REPAIR	17	
84	7	L0E-L2E	@ L0E	91	16% S.L. (SEE DETAIL 13)	REPAIR	17	
113	7	L0W-L1W	@ L0W	92	18% S.L., (SEE DETAIL 23)	REPAIR	19	
65	7	L0E – L1W	@ L0E	88	50% S.L., 3" X 6" HOLE IN BOT. CONN PL.	REPAIR	15	
114	7	U1E-L2E	@ L2E	93	17% S.L., (SEE DETAIL 3)	REPAIR	19	
38	7	L1E - L2E	@ L2E BOT. OUTSIDE ANGLE	94	2 - PLUG WELDS	MONITOR	05	
115	7	L2W-L6W	FULL LENGTH	95	6% S.L., .49'' AVG. REM. PLATES 1/2'' NOM., .344 AVG. REM. ANGLES 3/8'' NOM.	MONITOR	19	
153	7	U2E-U3W	MIDSPAN	96	PLUG WELD	MONITOR	20	X
116	7	U2E-L3E	@ L3E	97	15% S.L., (SEE DETAIL 3)	MONITOR	19	
39	7	L3W U3W	2' ABOVE DECK	*2017	2 1" PLUG WELDS, O.S. CHAN FLG. & 5" X 3/4" OFFSET W/ 2 1/2" GOUGES IN BOT. STAY PL.	REPAIRED	11	
117	7	L3E – U4E	@ L3E	98	39% S.L., (SEE DETAIL 3)	REPAIR	19	
40	7	L3W – U4W	@ L3W	99	24% S.L., (SEE DETAIL 3)	REPAIR	13	
118	7	U3E-L4E	@ L4E	100	11% S.L., (SEE DETAIL 3)	REPAIR	19	
119	7	U3W-L4W	@ L4W	101	15% S.L., (SEE DETAIL 3)	REPAIR		
41	7	L4W U4W	2' ABOVE DECK	<u>*2017</u>	1" PLUG WELD OS CHAN. FLG.	REPAIRED		

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 YEAR: 2020

% S.L. SHOWN IS ESTIMATED

ITEM GRAN					Set I	DECOMMENDATION	or defici	licy
#	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН
120	7	L4E – U5E	@ L4E	102	17% S.L., (SEE DETAIL 3)	REPAIR	19	
121	7	L4W – U5W	@ L4W	103	16% S.L., (SEE DETAIL 3)	REPAIR	19	
122	7	U4E-L5E	@ L5E	104	21% S.L., (SEE DETAIL 3)	REPAIR	19	
123	7	U4W-L5W	@ L5W	105	14% S.L., (SEE DETAIL 3)	REPAIR	19	
124	7	L5E-U6E	@L5E	106	26% S.L., (SEE DETAIL 3)	REPAIR	19	
42	7	L6W - U6W	12' ABOVE DECK	107	2" X 1/4" OFFSET	MONITOR	05	
125	7	L6E-L8E	FULL LENGTH	108	7% S.L., .30" AVG. REM. PLATES 5/16" NOM., .33 AVG. REM. ANGLES 3/8" NOM.	MONITOR	19	
126	7	GUSSET PL.	L7E, OUTSIDE	109	15% S.L., (SEE DETAIL 21)	MONITOR	19	
127	7	L6W-L8W	FULL LENGTH	110	27% S.L., (SEE DETAIL 22) 70% S.L., 1 ST BATTEN PL. @ L8W, 3" X 7"L & 3" X 9"L HOLES	REPAIR	19	
128	7	U7W – L8W	@ L8W	111	40% S.L., BOT. STAY PL.2''L X 8'' HOLE. 2^{ND} & 4^{TH} LAT. BAR 2'' HOLES	MONITOR	19	
129	7	FB. 8	FULL LENGTH	112	18% S.L., BOT. FLG. 14% S.L., WEB 11% S.L., TOP FLG. (SEE DETAIL 26) 4" HOLES IN STIFF. @ S1 & S4, 1" HOLE IN STIFF. @ S3	REPAIR	19	
130	7,8	JOINT.	@ P 6	113	3' FAILED	REPAIR	19	X
43	7,8	CONDUIT	P 6, W. SIDE	114	CONDUIT BROKEN IN SEVERAL PLACES, INCLUDING JUNCTION BOX	REPAIR	13	
85	7,8	P6	WALL, COLUMN	115	20 SQ FT SPALL/DELAM WALL 20 SQ FT SPALL/DELAM COLUMN 4 SQ.FT. SPALL/DELAM CAP	MONITOR	17	
131	8	FB. 0	FULL LENGTH TO COVER PL.	112, 117	14% S.L., BOT. FLG. 4% S.L., TOP FLG. (SEE DETAIL 25)	REPAIR		
44	8	L0E – L1E	@ L0E	118	26% S.L. (SEE DETAIL 4)	REPAIR2		

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 YEAR: 2020

% S.L. SHOWN IS ESTIMATED

	* See report from year indicated for photo of deficiency								
ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН	
132	8	L0E – U1E	@ L0E, & 4' ABOVE L0E	119	LACING BARS 1-12 FROM BOT. CHORD HAVE 1"- 3" HOLES, MOST 100% S.L., 2 BARS BROKEN	MONITOR	19		
133	8	L0W-L1E	@ L0W	120	20% S.L., 12'' X 2'' HOLE IN CONN. PL.	MONITOR	19		
45	8	PORTAL FRAME	U1W U1E, 2' WEST OF CENTERLINE OF ROADWAY	* 2015	10" X 1" OFFSET	REPAIRED	07		
134	8	L1E-L2W	@ L2W	121	20% S.L., 7" X 2" HOLE IN CONN. PL.	MONITOR	19		
66	8	L2E – L3W	@ L3W	122	10%S.L., 5" X 2" HOLE IN BOT. CONN PL.	MONITOR	15		
135	8	L3E – U4E	2' FROM L3E	?	4% S.L., (SEE DETAIL 3)	MONITOR	19		
86	8	L3W-U4W	@ L3W	123	8% S.L., (SEE DETAIL 3)	MONITOR	17		
67	8	L3E – L4W	@ L4W	124	20% S.L., 4" X 7" & 2-1" HOLES IN BOT. CONN PL.	MONITOR	15		
68	8	GUSS. PL	@ L4W, O.S. PL.	125	5% S.L., .488" AVG REM. IN 12" X 3"AREA, & .625"NOM. (PL. 52"W X 5/8" THICKNESS)	MONITOR	15		
154	8	FB. 4	W END	126	15% S.L. IN WEB, 20% S.L. IN BOT. FLG. (SEE DETAIL 27)	MONITOR	20	X	
136	8	L4W – U5W	2' FROM L4W	127	5% S.L., .23 AVG REM INT. LEGS, 5/16" NOM.	MONITOR	19		
69	8	L4E – L5W	@ L5W	128	20% S.L., 4"L X 10" HOLE IN BOT. CONN PL.	MONITOR	15		
137	8	FB. 5	W. END	129	8% S.L., BOT. FLG. @ L5W CONN. PL., .695" REM., .85 NOM.	MONITOR	19		
70	8	U5E – U6W	@ MIDSPAN, PAN 6	130	14% S.L. 7/8" MISDRILLED HOLE	MONITOR	15		
46	8	L6W - U7W	20' ABOVE DECK	?	9" x ½" OFFSET	MONITOR	03		
87	8	L7W U7W	@ L7W, 8" ABOVE GUSSET	131	26% S.L. (SEE DETAIL 11)	REPAIRED 29% S.L., IRF= 0.63	17	X	
71	8	U7W – L8W	@ L8W, & 4' ABOVE L8W	132	30% S.L., 10" X 3"L & 2"L X 3" HOLES IN BATTEN PL., & LACING BARS 2-9 FROM BOT. CHORD HAVE 1"- 3" HOLES, MOST 100% S.L., 4 BARS BROKEN	MONITOR	15		

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR

REHABILATATION

In reference to stiffeners and cross frames, the first shall be on the pier or abut.

SN: 062-0036 YEAR: 2020

% S.L. SHOWN IS ESTIMATED

* See report from year indicated for photo of deficiency									
ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН	
138	8	L7W-L8W	@ L8W	133	22% S.L., (SEE DETAIL 20)	REPAIR	19		
139	8	L7E-L8E	@ L8E	134	22% S.L., (SIM. TO DETAIL 20)	REPAIR	19		
140	8	FB. 8	@ C.L., THROUGHOUT	135	19% S.L., TOP FLG., 7% S.L. BOT. FLG. (SEE DETAIL 24)	REPAIR	19	X	
141	8	E. BRG.	@ P7	136	1 NUT 90% S.L.	MONITOR	19		
47	8, 9	P. 7	PIER CAP ENDS, WALL & W TRUSS BRG.	137, 138, 139	17% LOSS OF BRG. (DETAIL 5), 300 SQ. FT. DELAM./SPALL CAP, 300 SQ. FT. DELAM./SPALL WALL	REPAIR	03		
142	9	B1	@ P7	140	19% S.L., (SEE DETAIL 9)	MONITOR	19		
143	9	B2	@ P7	141	6% S.L., (SEE DETAIL 9)	MONITOR	19		
144	9	В3	@ P7	142	11% S.L., (SEE DETAIL 9)	MONITOR	19		
145	9	B4	@ P7	143	3% S.L., (SEE DETAIL 9)	MONITOR	19		
49	9-13	BENT 3-6	@ BENT 3-6	151, 152, 153, 154	ALL PILES TILTED TO NORTH, 1.8 DEGREES @ BENT 3-6	MONITOR	05	X	
88	11	BEAM 1	@ BENT 5	144	27% S.L. WEB BRG. (SEE DETAIL 9)	REPAIR 19% S.L. WEB BRG., IRF=1.62	17		
146	11	DIAPH.	@ BENT 5 BTWN. BM. 1 & 2	145	WEB OF DIAPH. BUCKLED @ BM. 1	REPAIR	19		
89	11	BEAM 2	@ BENT 5	146	16% S.L. (SEE DETAIL 9)	REPAIR 17% S.L., IRF=1.49	17		
90	11	BEAM 3	@ BENT 5	147	9% S.L. (SEE DETAIL 9)	MONITOR 9% S.L., IRF=1.54	17		
91	11	BEAM 4	@ BENT 5	148	14% S.L. (SEE DETAIL 9)	RATE	17	X	
92	12	BEAM 1	@ BENT 5	144	45% S.L. (SEE DETAIL 9)	REPAIR 27% S.L., IRF=1.48	17		
93	12	BEAM 2	@ BENT 5	146	29% S.L. (SEE DETAIL 9)	REPAIR 14% S.L., IRF=1.38			
94	12	BEAM 3	@ BENT 5	147	41% S.L. (SEE DETAIL 9)	REPAIR 10% S.L., IRF= 1.33	17		

MONITOR – CONSIDER FOR REPAIR NEXT MAJOR


REHABILATATION


In reference to stiffeners and cross frames, the first shall be on the pier or abut.


SN: 062-0036 **YEAR: 2020**

% S.L. SHOWN IS ESTIMATED


ITEM #	SPAN	MEMBER	LOCATION	РНОТО	DEFICIENCY	RECOMMENDATION BY SPN	YR	СН
95	12	BEAM 4	@ BENT 5	148	18% S.L. (SEE DETAIL 9)	RATE 8% S.L., IRF= 1.36	17	X
48	11, 12	BENT 5	ALL PILES	149, 150	25% S.L. PILE VERT. BARS 100% S.L. TIES 30% S.L. PILE CONCRETE (SEE DETAIL 6)	REPAIR	05	X
50	12, 13	BENT 6	PILE 2, & PILE 3 (PILES NUMBERED FROM EAST TO WEST)	155	19% S.L., 6 SQ. FT. DELAM./SPALL W/ EXP. BARS ON PILE 2, & 6 SQ. FT. DELAM./SPALL W/ EXP. BARS, 2 VERT. EXP. & 1 TIE ON PILE 3 (SEE DETAIL 8)	MONITOR	09	X
51	14	JUNCTION BOX	@ S. ABUT., E. SIDE	156	NO COVER ON BOX, CONDUIT BROKEN	REPAIR	13	
52	14 APPROACH © S. ABUT.		157	24 SQ. FT. DELAM./ SPALL	REPAIR	09	X	











	SPAN																	
SPAN	MEMBER	А	В	С	D	Е	F	G	Н	I	J	K	L	М	N	0	Р	% S.L.
3	L3E-U4E	0.17	0.17	0.27	0.26	0.24	0.26	0.31	0.31	0.23	0.24	0.31	0.31	0.25	0.25	0.31	0.31	16%
6	U2E-L3E	0.31	0.30	0.23	0.22	0.31	0.31	0.31	0.24	0.27	0.23	0.28	0.28	0.27	0.27	0.25	0.27	13%
6	L3E-U4E	0.21	0.26	0.29	0.30	0.33	0.32	0.28	0.28	0.31	0.31	0.30	0.31	0.31	0.31	0.29	0.31	6%
6	U3E-L4E	0.31	0.31	0.31	0.31	0.22	0.20	0.19	0.26	0.31	0.31	0.31	0.31	0.31	0.31	0.31	0.31	9%
6	L4E-U5E	0.31	0.31	0.31	0.31	0.24	0.20	0.21	0.26	0.31	0.31	0.31	0.31	0.31	0.31	0.31	0.31	8%
6	U4E-L5E	0.31	0.31	0.29	0.31	0.30	0.30	0.26	0.19	0.31	0.30	0.29	0.27	0.25	0.24	0.26	0.27	10%
7	U1E-L2E	0.24	0.26	0.29	0.31	0.30	0.31	0.31	0.31	0.24	0.24	0.24	0.24	0.20	0.22	0.20	0.17	17%
7	U2E-L3E	0.27	0.22	0.27	0.31	0.29	0.31	0.31	0.31	0.24	0.26	0.27	0.23	0.22	0.22	0.23	0.24	15%
7	L3E-U4E	0.12	0.14	0.12	0.11	0.21	0.15	0.31	0.31	0.16	0.12	0.20	0.24	0.20	0.19	0.24	0.24	39%
7	L3W-U4W	0.12	0.14	0.31	0.31	0.29	0.29	0.31	0.31	0.29	0.25	0.22	0.24	0.19	0.20	0.17	0.21	22%
7	U3W-L4W	0.27	0.29	0.31	0.31	0.13	0.21	0.31	0.31	0.24	0.25	0.28	0.31	0.28	0.25	0.25	0.22	15%
7	U3E-L4E	0.21	0.21	0.31	0.31	0.30	0.31	0.31	0.31	0.29	0.30	0.25	0.28	0.28	0.25	0.22	0.28	11%
7	U4W-L5W	0.29	0.31	0.31	0.31	0.26	0.16	0.32	0.30	0.27	0.25	0.24	0.26	0.19	0.24	0.23	0.31	14%
7	L4W-U5W	0.25	0.25	0.31	0.31	0.29	0.29	0.21	0.31	0.27	0.29	0.26	0.22	0.18	0.24	0.21	0.24	16%
7	L4E-U5E	0.24	0.23	0.31	0.31	0.30	0.31	0.31	0.31	0.22	0.23	0.25	0.24	0.22	0.21	0.19	0.16	17%
7	U4E-L5E	0.21	0.17	0.31	0.31	0.23	0.19	0.20	0.35	0.29	0.24	0.20	0.30	0.26	0.31	0.19	0.20	21%
7	L5E-U6E	0.17	0.17	0.29	0.31	0.18	0.08	0.29	0.32	0.25	0.23	0.26	0.27	0.23	0.21	0.21	0.22	26%
8	L3W-U4W	0.31	0.31	0.31	0.31	0.14	0.14	0.31	0.31	0.31	0.31	0.31	0.31	0.31	0.31	0.31	0.31	8%
8	L3E-U4E	0.31	0.31	0.31	0.31	0.27	0.27	0.27	0.27	0.31	0.31	0.31	0.31	0.31	0.31	0.31	0.31	4%















TABLE 9


SPAN	BM	А	В	С	S.L
9	1	0.36	0.35	0.34	19%
9	2	0.40	0.41	0.40	6%
9	3	0.38	0.38	0.39	11%
9	4	0.40	0.41	0.44	3%
11	1	0.34	0.32	0.28	27%
11	2	0.35	0.36	0.37	16%
11	3	0.40	0.39	0.39	9%
11	4	0.38	0.36	0.37	14%
12	1	0.28	0.23	0.20	45%
12	2	0.30	0.32	0.30	29%
12	3	0.25	0.24	0.27	41%
12	4	0.36	0.35	0.35	18%


TABLE 10


MISSING GUARDRAIL BOLTS


<u>SPAN</u>	<u>MEMBER</u>	LOCATION	DEFIENCY	<u>РНОТО</u>
3	RAIL	1 ST POST N OF L6W	2 MISSING BOLTS	1 <u>58</u>
4	RAIL	2 ND POST S OF L5W	2 MISSING BOLTS	159
5	RAIL	1 ST POST N & S OF L4W	2 MISSING BOLTS	160
8	RAIL	1 ST POST N OF L2W	2 MISSING BOLTS	161


















































PHOTO 1

SP 4 LOOKING NORTH



РНОТО 2

SP. 8, LOOKING SOUTH



РНОТО 3

SP. 6, LOOKING NORTH



PHOTO 4

SP. 6, LOOKING WEST



РНОТО 5

SP. 5, LOOKING SOUTH



РНОТО 6

SP. 4, LOOKING SOUTH



РНОТО 7

SP. 4, LOOKING SOUTH



РНОТО 8

SP. 13 LOOKING NORTH



РНОТО 9

SP. 6, LOOKING NORTH



РНОТО 10

SP.7, LOOKING NORTH



РНОТО 11

SP.8, LOOKING NORTH




РНОТО 12



РНОТО 13



РНОТО 14



РНОТО 15



РНОТО 16



PHOTO 17



PHOTO 18



РНОТО 19



РНОТО 20



РНОТО 21



РНОТО 22



PHOTO 23



PHOTO 24



РНОТО 25




PHOTO 26



РНОТО 27



РНОТО 28



РНОТО 29



РНОТО 30



РНОТО 31



РНОТО 32



РНОТО 33



РНОТО 34



РНОТО 35



РНОТО 36



РНОТО 37



PHOTO 38



РНОТО 39



РНОТО 40




PHOTO 41



PHOTO 42



РНОТО 43



РНОТО 44



PHOTO 45



PHOTO 46



РНОТО 47




РНОТО 48



РНОТО 49



РНОТО 50



РНОТО 51



PHOTO 52



РНОТО 53



PHOTO 54



РНОТО 55



PHOTO 56



PHOTO 57



PHOTO 58



PHOTO 59



PHOTO 60



PHOTO 61



PHOTO 62



РНОТО 63



РНОТО 64



РНОТО 65



РНОТО 66



РНОТО 67



РНОТО 68



PHOTO 69



РНОТО 70




PHOTO 71



PHOTO 72



РНОТО 73



РНОТО 74



РНОТО 75



РНОТО 76



РНОТО 77



PHOTO 78



РНОТО 79



РНОТО 80





РНОТО 82



РНОТО 83



РНОТО 84



PHOTO 85



PHOTO 86



РНОТО 87



PHOTO 88



РНОТО 89



РНОТО 90



РНОТО 91



РНОТО 92



РНОТО 93



РНОТО 94



РНОТО 95



PHOTO 96



РНОТО 97



РНОТО 98



РНОТО 99



PHOTO 100




PHOTO 101



PHOTO 102



PHOTO 103




PHOTO 104



PHOTO 105



PHOTO 106



PHOTO 107



PHOTO 108



PHOTO 109



PHOTO 110



PHOTO 111



PHOTO 112





PHOTO 114



PHOTO 115



PHOTO 116



PHOTO 117



PHOTO 118





PHOTO 120





PHOTO 122




PHOTO 123



PHOTO 124



PHOTO 125



PHOTO 126



PHOTO 127



PHOTO 128



PHOTO 129



PHOTO 130



PHOTO 131

REPAIRED



PHOTO 132



РНОТО 133



PHOTO 134



PHOTO 135



PHOTO 136



PHOTO 137



PHOTO 138



PHOTO 139



PHOTO 140



PHOTO 141



PHOTO 142



PHOTO 143



PHOTO 144



PHOTO 145



PHOTO 146



PHOTO 147



PHOTO 148



PHOTO 149



PHOTO 150



PHOTO 151



PHOTO 152



PHOTO 153



PHOTO 154



PHOTO 155



PHOTO 156



PHOTO 157



PHOTO 158



PHOTO 159



PHOTO 160



PHOTO 161
PHOTO 162

STRUCTURE NUMBER: 062-0036 DATE: 4/20/2020 DATE: BY:SMS BY: LOC. READING TEMP. JNT. LOC. LOC. **READING** TEMP. JNT. LOC. **TYPE** MEAS. **TYPE** MEAS. N. ABUT. 1 3/8" PJS Е PJS 52 N. ABUT. Ε P1 2 1/2" 52 PJS Ε P1 PJS Е **P2** 2 3/8" 52 NJ Ε **P2** NJ Е **P3** 2 3/4" 52 Ε **P3** NJ NJ Ε P4 4 1/4" 52 FP Ε P4 FP Е P5 3 1/8" 52 NJ Ε P5 NJ Ε 2 5/8" P6 52 NJ Ε P6 NJ Е **P7** 2 5/8" 52 PJS **P7** PJS Ε Ε **B4** 3 1/8" **52 PJS** Ε **B4 PJS** Ε 1 3/4" S. ABUT. 52 PJS Ε S. ABUT. PJS Ε ALL READINGS TAKEN 1' FROM PARAPET, CURB OR GUARD RAIL


			STR	UCTURE N	JMBER: 062-0	036				
DATE: 4/17/	/2017				DATE: 4/22/2	2010				
BY:CSE, TD					BY: SMS, JDD					
LOC.	READING	TEMP.	JNT. TYPE	LOC. MEAS.	LOC.	READING	TEMP.	JNT. TYPE	LOC. MEAS.	
N. ABUT.	1"	63	PJS	Е	N. ABUT.	1 1/4"	67	PJS	Е	
P1	2 1/4""	63	PJS	Е	P1	2 1/4"	67	PJS	Е	
P2	2 3/8"	63	NJ	Е	P2	2 1/2"	67	NJ	Е	
P3	2 3/4"	63	NJ	Е	P3	2 1/2"	67	NJ	Е	
P4	4 1/4"	65	FP	Е	P4	3 7/8"	67	FP	Е	
P5	3"	68	NJ	E	P5	2 3/4"	67	NJ	E	
P6	2 1/2"	68	NJ	E	P6	2 3/8"	67	NJ	E	
P7	1 7/8"	68	PJS	E	P7	2 3/8"	67	PJS	E	
B4	2 1/4"	68	PJS	Е	B4	2 3/4"	67	PJS	E	
S. ABUT.	1 3/8"	68	PJS	E	S. ABUT.	1 3/8"	67	PJS	E	
					1					
		†			1					
<u>-</u>										
					1					
	,	ALL READ	INGS TAKE	N 1' FROM	PARAPET, CU	RB OR GUAR	D RAIL			

			STR	UCTURE N	JMBER: 062-0	036				
DATE: 4/16/	/2013				DATE: 4/15/2	2015				
BY: KCG	2013				BY: CSE, EMR, CJI					
LOC.	READING	TEMP.	JNT. TYPE	LOC. MEAS.	LOC.	READING	TEMP.	JNT. TYPE	LOC. MEAS.	
N. ABUT.	1 1/8"	51	PJS	Е	N. ABUT.	1"	48	PJS	Е	
P1	2 1/2"	51	PJS	Е	P1	2 1/4"	48	PJS	Е	
P2	2 1/4"	51	NJ	Е	P2	2 3/4"	48	NJ	Е	
P3	2 7/8"	51	NJ	Е	P3	3 1/4"	48	NJ	E	
P4	4 5/8"	51	FP	E	P4	4 7/8"	48	FP	Е	
P5	3"	51	NJ	E	P5	3 1/4"	48	NJ	E	
P6	3"	51	NJ	Е	P6	3"	48	NJ	E	
P7	2 3/8"	51	PJS	Е	P7	2 1/4"	48	PJS	E	
B4	2 7/8"	51	PJS	Е	B4	2 5/8"	48	PJS	E	
S. ABUT.	1 1/4"	51	PJS	E	S. ABUT.	1 1/4"	48	PJS	E	
		ALL READ	INGS TAKE	N 1' FROM	PARAPET, CU	RB OR GUAR	D RAIL			

DATE: 4/20)/2009				DATE: 4/28/2011						
BY: CMV					BY: MEL						
LOC.	READING	TEMP.	JNT. TYPE	LOC. MEAS.	LOC.	READING	TEMP.	JNT. TYPE	LOC. MEAS		
N. ABUT.	7/8"	52	PJS	E	N. ABUT.	7/8"	55	PJS	E		
P 1	2 3/8"	52	PJS	E	P1	2 1/4"	55	PJS	E		
22	2 ½"	52	NJ	E	P2	2 ½"	55	NJ	E		
23	3"	52	NJ	E	P3	3"	55	NJ	E		
4	4 ½"	52	FP	E	P4	4 1/2"	55	FP	E		
25	3"	52	NJ	E	P5	3"	55	NJ	E		
6	2 7/8"	52	NJ	E	P6	2 5/8"	55	NJ	E		
2 7	2 3/8"	52	PJS	E	P7	2 1/4"	55	PJS	E		
34	2 3/4"	52	PJS	E	B4	2 3/4"	55	PJS	E		
S. ABUT.	1"	52	PJS	E	S. ABUT.	1"	55	PJS	E		
								1			
	1										
					1		1		1		

			STR	UCTURE N	JMBER: 062-0	036					
DATE: 05/2	2/05				DATE: 06/04/07						
BY: SKP	3/03				BY: DLH						
DI. SKF					DT. ULN						
LOC.	READING	TEMP.	JNT.	LOC.	LOC.	READING	TEMP.	JNT.	LOC.		
LOC.	READING	I CIVIF.	TYPE	MEAS.	LOC.	READING	I EIVIF.	TYPE	MEAS.		
N. ABUT.	1"	68	PJS	W W	N. ABUT.	1"	70	PJS	W W		
P1	2 ½"	68	PJS	W	P1	2 5/8"	70	PJS	W		
P2	2 1/4"	68	NJ	W	P2	2 5/8"	70	NJ	W		
P3	2 3/4"	68	NJ	W	P3	2 3/4"	70	NJ	W		
P4	3 5/8"	68	FP	W	P4	3 3/4"	70	FP	W		
P5	3"	68	NJ	W	P5	3 1/8"	70	NJ	W		
P6	2 ½"	68	NJ	W	P6	2 7/8"	70	NJ	W		
P7	2 1/8"	68	PJS	W	P7	2 1/0	70	PJS	W		
B4	2 3/4"	68	PJS	W	B4	2 3/4"	70	PJS	W		
S. ABUT.	1 1/2"	68	PJS	W	S. ABUT.	1 1/4"	70	PJS	W		
3. ADO1.	1 /2	00	F 0 0	***	3. ADO1.	1 /4	70	F33	***		
					+		+				
					+						
					1						
					1						
					†		+				
					+						
				 	+						
					1						
	_	<u> </u>		<u> </u>							
	A	LL READI	NGS TAKE	N 1' FROM	PARAPET, CU	IKR OK GUAF	KU KAIL				

			STR	JCTURE NU	JMBER: 062-0	036				
DATE: 05/0	7/01				DATE: 05/13/03					
BY: JLF	7701				BY: PTW					
B1.02.										
LOC.	READING	TEMP.	JNT.	LOC.	LOC.	READING	TEMP.	JNT.	LOC.	
			TYPE	MEAS.				TYPE	MEAS.	
N. ABUT.	1"	70	PJS	W	N. ABUT.	5/8"	62	PJS	Е	
P1	2 ½"	70	PJS	W	P1	2 3/4"	62	PJS	Е	
P2	2 5/8"	70	NJ	W	P2	2 3/4"	62	NJ	Е	
P3	3"	70	NJ	W	P3	3"	62	NJ	W	
P4	4 1/4"	70	FP	W	P4	4"	62	FP	W	
P5	3 1/4"	70	NJ	W	P5	3 1/4"	62	NJ	W	
P6	3"	70	NJ	W	P6	2 5/8"	62	NJ	W	
P7	2 1/8"	70	PJS	W	P7	2 1/4"	62	PJS	W	
B4	2 ½"	70	PJS	W	B4	2 3/4"	62	PJS	W	
S. ABUT.	1 1/8"	70	PJS	W	S. ABUT.	1 1/4"	62	PJS	W	
	ļ									
	Α	LL READI	NGS TAKE	N 1' FROM	PARAPET, CL	JRB OR GUAF	RD RAIL		•	





Attachment D. Top and Bottom of Deck Condition Surveys

Not Available.

Attachment E. Substructure Condition Surveys

See Attachment C, NBIS Inspection Report.

Attachment F. Cost Estimates

Preliminary cost discussion has been provided in the Recommendation section.

Attachment G. Proposed Structure

A proposed plan, elevation and cross section will be established as part of a replacement structure type study and TS&L development within the Phase I process for bridge replacement.

With regard to typical section, similar low-volume major river bridge replacements of recent decades have provided two 12' lanes and two 8' shoulders, for a face-to-face parapets dimension of 40', and an out-to-out deck width of 43'-2". (Using the 1'-5" constant slope barrier of All Bridge Designer Memo 19.1, this reduces to 42'-10".) See Figure G-1




Figure G-1 -- Typical section across structure.

The need and justification for inclusion of a Shared Use Path has not been established yet. If inclusion is established, the design of the structure will comply with applicable policies.



Attachment H. Structure Photos

For additional photos, see Attachment C, Inspection Report.



Photo 1 - Looking south from Henry. Approach spans 1 and 2 and truss span 3. Note posting sign restricting bridge to legal loads only.





Photo 2 - Looking south from Cromwell Dr. in Henry.





Photo 3 - Looking west. Spans 3 (partial at right), 4, 5 (navigation), and 6 leading into the trees on the south bank at left.



Photo 4 - Looking west. Truss spans 3 and 4. Cromwell Dr. passes under span 3 at right.





Photo 5 - Looking east. A tow of covered hopper barges being pushed upstream through truss span 5.





Photo 6 - Looking east (upstream). Abandoned lock from former dam at left, Henry marina at far left.



Photo 7 - Looking west (downstream). Henry waterfront and grain elevator at right.





Photo 8 - Looking north. Entering Henry from the bridge.



Attachment I. Hydraulic Analysis Summary

Hydraulic analyses will be performed as part of the Phase I process.

Attachment J. Proposed Plan & Profile

Design criteria and acceptable plan and profile will be established as part of the Phase I process.

Attachment K. Existing and Proposed Roadway Cross Sections

Proposed roadway cross section will be developed as part of the Phase I process.

Attachment L. Abbreviated Existing Plans

- 1. General Plan and Elevation 1988 Redeck and Rehabilitation
- 2. Deck Cross Sections 1988 Redeck and Rehabilitation
- 3. General Plan and Elevation 1933 Original Construction

